MEMO

DATE: 11-6-97

TO: file

SUBJECT: Alleghany Co. closed LF. site visit.

- site visit conducted in p.m. Met w/ Don Adams (new Co. manager) & Brent Rockett @ site. New MW installed @ proposed location. Erosion has taken place beneath one edge of the well pad.

- According to site GW data the UG MW has indicated gw contamination in this area. 2 possible sources:
  1) MW installed @ edge of waste or very near it, & mounding on LFG is the mechanism for contamination.
  2) Oil recycling drop off is near UG MW, as is a fuel oil tank (above ground). Staining from spillage is obvious @ both locations

From:

Photos were made during site visit.