



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>										
Lined MSWLF		LCID	<b>X</b>	YW		Transfer		Compost	SLAS	<b>COUNTY: CABARRUS</b> <b>PERMIT NO.: 13-F</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

**Date of Site Inspection:** 6/3/14

**Date of Last Inspection:** 7/19/11

**FACILITY NAME AND ADDRESS:**

Morehead LCID, LLC (Formerly Cabarrus County LCID, LLC)  
 5001 Morehead Road  
 Concord, North Carolina 28027

**GPS COORDINATES:** N: 35.34704 W: -80.67490

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Doug Foster, President  
 Telephone: (704) 455-3466  
 Email address: fostergrading@ctc.net

**FACILITY CONTACT ADDRESS:**

8752 Overcash Road  
 Concord, North Carolina 28027

**PARTICIPANTS:**

Doug Foster, President-Morehead LCID, LLC  
 Corky McClure, Cabarrus County LCID, LLC  
 John Murray, NCDENR-Solid Waste Section  
 Teresa Bradford, NCDENR-Solid Waste Section

**STATUS OF PERMIT:**

The Permit to Construct the North Disposal Area and the Permit to Operate Unit 1 and the North Disposal Area was issued on June 11, 2014. The Permit to Operate expires on June 11, 2019.

**PURPOSE OF SITE VISIT:**

Pre-Operational Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

None

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The Permit to Operate is issued to Charlotte Motor Speedway (CMS), LLC as the landowner and Morehead LCID, LLC as the operator and leaser. The facility was formerly operated by Cabarrus LCID Landfill, LLC.
2. The purpose of the inspection was to conduct a pre-operational inspection of the North Disposal Area, Unit 1.
3. The facility is permitted to receive land clearing waste, yard trash, untreated and unpainted wood, uncontaminated soil, inert debris such as unpainted rock, brick, concrete and concrete block; and asphalt in accordance with North Carolina General Statute (NCGS) 130-294(m). Wooden pallets as defined in the NCGS Article 9, Chapter 130A-290(44a) are not permitted for disposal.
4. The service area for the facility is Cabarrus County and surrounding counties in North Carolina.
5. The correct signage was located at the new entrance to the facility.
6. A gate is located at the new entrance to the facility to prevent unauthorized access.
7. Waste boundary markers were observed around the North Disposal Area.
8. Cover requirements were discussed during the inspection. As stated in Permit Condition No. 10, solid waste must be covered with 1 foot of suitable soil cover at least once per month or when the active area reaches 1 acre in size, whichever occurs first, or more often when necessary to prevent the site from becoming a nuisance or to mitigate conditions associated with fire, windblown materials, vectors or excessive water filtration.
9. Closure requirements for the existing landfill were discussed with Corky McClure, former operator of Cabarrus County LCID Landfill. Within 120 calendar days after completion of the final disposal operations, the disposal area must be closed and covered with a minimum of 1 foot of suitable cover sloped to allow surface water runoff in a controlled manner. According to Mr. McClure, soil cover has been placed, but additional grading is needed.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (704) 235-2160

---

Teresa N. Bradford  
 Environmental Senior Specialist  
*Regional Representative*

Sent on: <u>7/21/14</u>	<input checked="" type="checkbox"/>	Email		Hand delivery		US Mail		Certified No. [ ]
-------------------------	-------------------------------------	-------	--	---------------	--	---------	--	-------------------

cc: Jason Watkins, Field Operations Branch Head  
 Sarah Rice, Compliance Officer  
 Corky McClure, Cabarrus County LCID Landfill