



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:										
Lined MSWLF		LCID		YW		Transfer		Compost	SLAS	COUNTY: COLUMBUS PERMIT NO.: 24-01 FILE TYPE: COMPLIANCE
Closed MSWLF	X	HHW		White goods		Incineration		T&P	FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

Date of Site Inspection: February 25, 2015 **Date of Last Inspection:** August 25, 2014

FACILITY NAME AND ADDRESS:

Columbus County Closed MSWLF
 Landfill Road
 Whiteville, North Carolina 28472

GPS COORDINATES: N: 34.29330 W: 78.75123

FACILITY CONTACT NAME AND PHONE NUMBER:

Mr. Danny Fowler, Public Utilities Director
 910.642.2828

FACILITY CONTACT ADDRESS:

William Clark, County Manager
 111 Washington Street
 Whiteville, NC 28472
 bclark@columbusco.org

Mr. Danny Fowler, Public Utilities Director
 612 North Madison Street
 Whiteville, North Carolina 28472
 dfowler@columbusco.org

PARTICIPANTS:

Wes Hare, NCDENR Solid Waste Section

STATUS OF PERMIT:

Unlined MSWLF closed in 1998

PURPOSE OF SITE VISIT:

Partial Inspection

STATUS OF PAST NOTED VIOLATIONS:

Not applicable

OBSERVED VIOLATIONS

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The site is secured with a gate at the entrance and has controlled access for safety.
2. All entrance and haul roads are being maintained so as to provide all-weather access.
3. The landfill side slopes and cap are being maintained so as to prevent erosion.
4. Erosion control measures are being utilized, with no offsite sedimentation noted.
5. All monitoring wells observed were locked, as required.



Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 910.796.7405

 Wes Hare
 Environmental Senior Specialist
Regional Representative

Sent on: 2/26/15	X	Email		Hand delivery		US Mail	Certified No.
------------------	---	-------	--	---------------	--	---------	---------------

Copies: * Dennis Shackelford, Eastern District Supervisor
 * Jessica Montie, Compliance Officer