



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		<b>COUNTY:</b> Cumberland <b>PERMIT NO.:</b> 2602-MSWLF-1981 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF	<b>X</b>	HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** February 5, 2015

**Date of Last Inspection:** November 20, 2014

**FACILITY NAME AND ADDRESS:**

Fort Bragg Closed MSWLF  
 Longstreet Road, Fort Bragg

**GPS COORDINATES:** N: 35.1438 E: -79.07399

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Sid Williamson, Solid Waste Manager  
 Telephone: 910-396-3372  
 Email address: Sidney.d.williamson.civ@mail.mil  
 Fax: 910-396-4188

**FACILITY CONTACT ADDRESS:**

Department of the Army  
 Public Works Business Center  
 IMSE-BRG-PW  
 HQ, US Army Garrison, Fort Bragg  
 Installation Management Agency Command  
 Fort Bragg, North Carolina 28310

**PARTICIPANTS:**

Drew Hammonds, NCDENR-DWM  
 Sid Williamson, Fort Bragg Solid Waste Manager  
 Diane Adams, NCDENR-DEMLR  
 Jim Duncan, Fort Bragg Storm Water Staff

**STATUS OF PERMIT:**

MSWLF Closed May 2001

**PURPOSE OF SITE VISIT:**

Joint Inspection with DEMLR and Bragg Staff

**STATUS OF PAST NOTED VIOLATIONS:** NA

**OBSERVED VIOLATIONS**

1. None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. It appeared that additional mowing of tall vegetation at the facility had been conducted at the time of this inspection.
2. It is recommended that staff routinely mow the entire site as part of routine maintenance in order to check the integrity of the landfill cap for issues such as **settling and ponding of water, erosion, seeps, releases or any other issues** that cannot be observed due to high, thick vegetation.
3. Bragg solid waste personnel had begun removing the rip rap stone and filling the south side drainage ditch. The south ditch was approximately 2/3 complete at the time of this inspection. **This area did not appear to have changed from the November inspection of the site.**
4. Measures to prevent onsite erosion from the fill activity and to assist in establishing vegetative cover on this area need to be underway **as recommended in the November inspection report.**
5. There are some deeply settled and eroded areas on the landfill near the southeast corner where the cover had been mowed. **Bare and eroded areas should be repaired as soon as practical once they are observed.**
6. The road around the west end of the landfill was impassable due to large stockpile of soil that needs stabilization.
7. Corrective measures are necessary and should be completed within 30 days receipt of this inspection report.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 910-433-3350 email: [andrew.hammonds@ncdenr.gov](mailto:andrew.hammonds@ncdenr.gov)

Environmental Senior Specialist  
*Regional Representative*

Sent on: February 19, 2015	X	Email		Hand delivery		US Mail	Certified No. [ ]
----------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor  
 Jessica Montie, Solid Waste Section Compliance Officer  
 Audrey Oxendine, Fort Bragg Compliance Branch Chief  
 Sid Williamson, Fort Bragg Solid Waste Manager



South side drainage ditch, middle to east end.



South side drainage ditch repair west end.