



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW	X	Transfer		Compost		SLAS		COUNTY: Cumberland PERMIT NO.: 26G-LCID-1987 FILE TYPE: COMPLIANCE
Closed LCID	X	HHW		White goods		Incin		T&P	X	FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: February 5, 2015

Date of Last Inspection: November 20, 2014

FACILITY NAME AND ADDRESS:

Fort Bragg C&D Landfill
Lamont Road, Fort Bragg

GPS COORDINATES: N: 35.14381 E: -79.07399

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Sid Williamson, Solid Waste Manager
Telephone: 910-396-3372
Email address: Sidney.d.williamson.civ@mail.mil
Fax: 910-396-4188

FACILITY CONTACT ADDRESS:

Department of the Army
Public Works Business Center
IMSE-BRG-PW
HQ, US Army Garrison, Fort Bragg
Installation Management Agency Command
Fort Bragg, North Carolina 28310

PARTICIPANTS:

Drew Hammonds, NCDENR
Sid Williamson, Fort Bragg Solid Waste Manager

STATUS OF PERMIT:

Facility closed 2005.

PURPOSE OF SITE VISIT:

Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

NA

OBSERVED VIOLATIONS

1. None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 3

Additional Comments:

Yard Waste Area

1. There were several windrows of ground material on site for processing.
2. Ensure to turn and monitor rows for overheating. One row of yard trash was steaming pretty well at the time of this inspection.

Concrete Stockpile/Crushing Area

3. Concrete continues to be collected in the stockpile area.
4. The crushing of concrete was ongoing at the time of this inspection.
5. Efforts to continue to reduce the concrete stockpile should continue.

6. The side slopes had not been mowed as of the last inspection. The side slopes need mowing in order to perform inspections of the landfill to ensure the integrity of the cap and cover.
7. The facility is collecting recyclable metals adjacent to the crushed concrete.

Please contact me if you have any questions or concerns regarding this inspection report.

Environmental Senior Specialist
Regional Representative

Phone: 910-433-3350 Email: Andrew.hammonds@ncdenr.gov

Sent on: February 19, 2015	X	Email		Hand delivery		US Mail		Certified No. []
----------------------------	---	-------	--	---------------	--	---------	--	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor (email)
Jessica Montie, Solid Waste Section Compliance Officer (email)
Sid Williamson, Fort Bragg Solid Waste Manager (email)
Audrey Oxendine, Fort Bragg Compliance Branch Chief (email)