



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID	<b>X</b>	YW		Transfer		Compost		SLAS	<b>COUNTY:</b> Edgecombe <b>PERMIT NO.:</b> 33D <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection: April 27, 2015**

**Date of Last Inspection: June 6, 2002**

**FACILITY NAME AND ADDRESS:**

Barnhill Contracting-Asphalt Plant LCID  
 Gay Rd.  
 Rocky Mount, North Carolina

**GPS COORDINATES:** N: 35.96411 W: 77.72612

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Buddy Rose  
 Telephone: 252 824 8235 cell 252 883 6200  
 Email address: [brose@barnhillcontracting.com](mailto:brose@barnhillcontracting.com)  
 Fax: 252 824 8276

**FACILITY CONTACT ADDRESS:**

Barnhill Contracting  
 P.O. Box 1529  
 Tarboro, North Carolina 27886

**PARTICIPANTS:**

Ben Barnes NCDENR Solid Waste Section  
 Buddy Rose Barnhill Contracting

**STATUS OF PERMIT:**

Expired and the facility is closed. Permit issued January 30, 1996.

**PURPOSE OF SITE VISIT:**

Inspection of closed LCID landfill

**STATUS OF PAST NOTED VIOLATIONS:**

**15A NCAC 13B .0566 OPERATIONAL REQUIREMENTS FOR LAND CLEARING AND INERT DEBRIS LANDFILL**

Land Clearing and Inert Debris (LCID) landfills shall meet the following operational requirements:

(5) 120 calendar days after completion of any phase of disposal operations, or upon revocation of a permit, the disposal area shall be covered with a minimum of one foot of suitable soil cover sloped to allow surface water runoff in a controlled manner. The Division may require further action in order to correct any condition which is or may become injurious to the public health, or a nuisance to the community. **Not resolved:** *Documentation for the final closure of the landfill has not been found at this time. See item 4 in the comments section.*

**OBSERVED VIOLATIONS**

**NONE**

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 4

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS:**

1. The landfill has apparently not received waste for some time. The site was covered with vegetation of various types and sloped to drain.
2. No evidence of leachate, onsite or offsite erosion was observed.
3. The inspection report dated June 6, 2002 included a violation notice of an expired permit. The inspection report required Barnhill Contracting to either submit an application for a new permit or close the site according to Division requirements. A search of Division files did not produce any documentation of closure approved by the Division.
4. If documentation of Division approved closure cannot be found, 33D must be closed in accordance with 15A NCAC 13B .0566 (5) as landfill operations have been discontinued. In order to complete closure, within 45 days of receipt of this letter, submit a letter of certification, signed by a North Carolina licensed professional engineer, that a minimum of one foot of suitable soil cover has been placed over the entire landfill (utilizing at least 4 random test holes per acre). Within 60 days of receipt of this letter, submit a certified copy of the attached Closure Letter. Documentation of recordation of Permit Number 33D must also be submitted

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 252 236 4453 Email: [ben.barnes@ncdenr.gov](mailto:ben.barnes@ncdenr.gov)

*Ben Barnes*  
 Environmental Senior Specialist  
**Regional Representative**

Sent on: May 11, 2015	X	Email		Hand delivery		US Mail	Certified No. [ ]
-----------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Jason Watkins, Field Operations Branch Head  
 Dennis Shackelford, Eastern District Supervisor  
 Jessica Montie, Compliance Officer

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 4



Views of the top of the landfill



View of the top of the landfill



View of the southern slope of the landfill



View of the eastern end of the landfill, there does not appear to be any contact with waste and the pond

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 4 of 4



Approximate area of landfill