



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	COUNTY: Jones PERMIT NO.: 5202-TP-2012 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		C&D T&P	<input checked="" type="checkbox"/>	FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: 6 November 2014 **Date of Last Inspection:** 21 October 2014

FACILITY NAME AND ADDRESS:
 Maysville C&D Recycling & Recovery Facility
 11710 NC Highway 17
 Maysville, NC 28555

GPS COORDINATES: N: 34.92756 E: -077.24197

FACILITY CONTACT NAME AND PHONE NUMBER:
 James E Maides
 910.938.5900

FACILITY CONTACT ADDRESS:
 Green Recycling Solutions, LLC
 166 Center Street
 Jacksonville, NC 28546
 E-mail: jamesmaides@csbenc.com

PARTICIPANTS:
 Richard Howard; Metaltech Systems
 Ray Williams; DENR-Solid Waste

STATUS OF PERMIT:
 Active: Permit to Construct (PTC) a Construction and Demolition (C&D) Waste Treatment and Processing (T&P) Facility issued 25 February 2013.

PURPOSE OF SITE VISIT:
 Partial Facility Compliance Inspection without records review

STATUS OF PAST NOTED VIOLATIONS:
 None applicable

OBSERVED VIOLATIONS:
 No violations were observed during this Facility Compliance Inspection; please see the ADDITIONAL COMMENTS section below.

- ADDITIONAL COMMENTS:**
- 1) This Facility is a Construction and Demolition (C&D) Waste Treatment and Processing (T&P) Facility.
 - 2) This Facility is recorded with the Jones County Register of Deeds at: Book 351; Page 256.
 - 3) This Facility is permitted to receive C&D waste generated within Jones, Craven, Carteret, Onslow, Duplin, and Lenoir Counties.
 - 4) Construction of the C&D T&P Facility has been completed.
 - 5) This Facility is permitted to receive up to 400 tons of C&D waste per day for processing.
 - 6) This Facility has not begun receiving waste.
 - 7) The Facility access road is of all-weather construction and is being well maintained at this time.
 - 8) Facility operations were discussed during this Facility Compliance Inspection.
 - 9) The materials processing/sorting plant was in operation for testing during this Facility Compliance Inspection.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

5202-20141106INSP

Page 2 of 3



- 10) All sorting and processing equipment and operations were demonstrated during this Facility Compliance Inspection. The processing plant appears to be functioning properly at this time.
- 11) All paving and grading operations have been completed.



- 12) Erosion control measures were in place and appear to be functioning properly.
- 13) No off-site erosion was observed during this Facility Compliance Inspection.
- 14) The stormwater management pond was reviewed. The pond was clear of debris and all banks were vegetated with no erosion observed.
- 15) No violations were observed during this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection report.

Ray Williams

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

5202-20141106INSP

Page 3 of 3

Regional Representative

Delivered on : <u>7 November 2014</u> by	X	Electronic delivery		US Mail		Certified No. []
---	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
Jessica Montie; Chief Compliance Officer/SWS: Jessica.montie@ncdenro.gov
Franky J Howard; Jones County Manager: fhoward@co.jones.nc.us

C: \\2014\Jones\Facilities\52-02\Inspections\5202-20141106INSP
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>



 Go Green! Thank you for helping NCDENR be environmentally responsible.