



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		COUNTY: Jones PERMIT NO.: 5203-CDLF-2013 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		C&D T&P	<input checked="" type="checkbox"/>	FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDF		

**Date of Site Inspection:** 1 December 2014

**Date of Last Inspection:** 25 November 2014

**FACILITY NAME AND ADDRESS:**

Maysville Construction and Demolition Debris Landfill  
 11710 NC Highway 17  
 Maysville, NC 28555

**GPS COORDINATES:** N: 34.93213 E: -077.24436

**FACILITY CONTACT NAME AND PHONE NUMBER:**

James E Maides  
 910.938.5900

**FACILITY CONTACT ADDRESS:**

Green Recycling Solutions, LLC  
 166 Center Street  
 Jacksonville, NC 28546  
 E-mail: [jamesmaides@csbenc.com](mailto:jamesmaides@csbenc.com)

**PARTICIPANTS:**

James Maides; Green Recycling Solutions  
 Kevin Dail; Green Recycling Solutions  
 Ray Williams; DENR-Solid Waste

**STATUS OF PERMIT:**

Active: Permit to Construct (PTC) Construction and Demolition (C&D) Landfill, Phase I issued 17 January 2014; expires 17 January 2019. The Permit to Operate (PTO) shall not be issued until the conditions listed in the PTC are accomplished.

**PURPOSE OF SITE VISIT:**

Partial Facility Compliance Inspection without records review

**STATUS OF PAST NOTED VIOLATIONS:**

None applicable

**OBSERVED VIOLATIONS:**

No violations were observed during this Facility Compliance Inspection; please see the ADDITIONAL COMMENTS section below.

**ADDITIONAL COMMENTS:**

- 1) This Facility is a Construction and Demolition (C&D) waste Landfill.
- 2) The Facility access road is of all-weather construction and is being well maintained at this time.
- 3) Construction of Cell I of the C&D Landfill was underway during this Facility Compliance Inspection.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

5203-20141201INSP

Page 2 of 3



- 4) Contract employees were on-site working on leachate sump installation during this Facility Compliance Inspection.



- 5) Installation of the synthetic liner system has been completed.



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

5203-20141201INSP

Page 3 of 3



- 6) Erosion control measures were in place and appeared to be functioning properly.
- 7) No off-site erosion was observed during this Facility Compliance Inspection.
- 8) Facility monitoring wells were reviewed. All well labels have been affixed and the wells were secured with functioning locks.
- 9) No violations were observed during this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection report.

*Ray Williams; Environmental Senior Specialist* Phone: 252.948.3955 E-mail: [ray.williams@ncdenr.gov](mailto:ray.williams@ncdenr.gov)

***Regional Representative***

<b>Delivered on :</b> <u>5 December 2014</u> <b>by</b>	X	Electronic delivery		US Mail		Certified No. <u>  </u>
--	---	---------------------	--	---------	--	-------------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: [dennis.shackelford@ncdenr.gov](mailto:dennis.shackelford@ncdenr.gov)  
 Jessica Montie; Chief Compliance Officer/SWS: [Jessica.montie@ncdenro.gov](mailto:Jessica.montie@ncdenro.gov)  
 Kevin Dail; Operations Supervisor/Green Recycling Solutions: [kdail.gwr@gmail.com](mailto:kdail.gwr@gmail.com)  
 Franky J Howard; Jones County Manager: [fhoward@co.jones.nc.us](mailto:fhoward@co.jones.nc.us)

C: \2014\Jones\Facilities\52-03\Inspections\5203-20141201INSP  
 NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>



 Go Green! Thank you for helping NCDENR be environmentally responsible.