



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>COUNTY: Macon</b> <b>PERMIT NO.: 57-01</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	<b>X</b>	HHW		White goods		Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection: August 13, 2014 Date of Last Inspection: December 15, 2011**

**FACILITY NAME AND ADDRESS:**

Franklin Sanitary Landfill  
 Radio Hill Road  
 Franklin, NC 28724

**GPS COORDINATES:** N: 35.20946 W: 83.36533

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Chris Stahl, Macon County Solid Waste Director  
 Telephone: (828) 349-2100  
 Email address: cstahl@mail.maconnc.org

**FACILITY CONTACT ADDRESS:**

109 Sierra Drive  
 Franklin, NC 28734

**PARTICIPANTS:**

Chris Stahl, Macon County Solid Waste Dept.  
 Troy Harrison, Environmental Senior Specialist

**STATUS OF PERMIT:**

Closure letter issued July 24, 1996  
 Closure Letter Amendment issued March 3, 2000  
 Post Closure Use of Landfill letter issued February 27, 2012

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Landfill operations ceased in January 01, 1993. All MSW waste has been taken, after that date, to the Macon County Landfill (Permit No. 57-03).
2. Vegetation was well established on top of the landfill and well maintained.
3. Ground water monitoring wells were observed. All monitoring wells observed appeared to be maintained in good condition and access. The methane monitoring wells that were observed and appeared to be in good condition.
4. No low or wet areas on the cap were observed.
5. A model airplane club utilizes the cap as an airfield. This activity was approved by way of a letter to Larry Lackey, former Macon County Solid Waste Director, on March 3, 2000 from Jim Coffey, Head, Permitting Branch/Solid Waste Section. The structures were weighted down with concrete and not driven into the ground.
6. A law enforcement shooting range is located next to the landfill in the old borrow area. Access to the range is via the road bed across the landfill. This activity was approved by the Solid Waste Section on February 27, 2012 by letter from Allen Gaither, Solid Waste Section Permitting Engineer.

Please contact me if you have any questions or concerns regarding this inspection report.

\_\_\_\_\_ Phone: (828) 296-4701

Environmental Senior Specialist  
***Regional Representative***

Sent on: August 20, 2014	X	Email		Hand delivery		US Mail		Certified No. [ ]
--------------------------	---	-------	--	---------------	--	---------	--	-------------------

Copies: Jason Watkins, Field Operations Branch Head  
Sarah Rice, Compliance Officer