



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		COUNTY: Stokes PERMIT NO.: 8503-INDUS- FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill	<input checked="" type="checkbox"/>	DEMO		SDTF		

**Date of Site Inspection:** 4/27/2015      **Date of Last Inspection:** 9/26/2013

**FACILITY NAME AND ADDRESS:**

Duke Energy Carolinas, LLC  
 Belews Creek Steam Station  
 Pine Hall Ash Landfill (Closed)  
 3195 Pine Hall Road  
 Belews Creek, North Carolina 27009

**GPS COORDINATES:** N: 36.28420 E: -80.07012

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Melonie Martin, Environmental Coordinator  
 Office: 336-445-0610, Cell: 336-669-2994  
 E-mail: [melonie.martin@duke-energy.com](mailto:melonie.martin@duke-energy.com)

Kimberlee Hutchinson, PE, Sr. Engineer - Environmental Services  
 Cell: 336-215-4576  
 E-mail: [kim.hutchinson@duke-energy.com](mailto:kim.hutchinson@duke-energy.com)

**FACILITY CONTACT ADDRESS:**

Duke Energy Carolinas, LLC  
 Belews Creek Steam Station  
 3195 Pine Hall Road  
 Belews Creek, North Carolina 27009

**PARTICIPANTS:**

Shawn McKee, NCDENR, Solid Waste Section, Environmental Senior Specialist  
 Hugh Jernigan, Solid Waste Section, Environmental Senior Specialist  
 Larry Frost, NCDENR, Solid Waste Section, Engineering Project Manager  
 Elizabeth Werner, NCDENR, Solid Waste Section, Permitting Hydrogeologist  
 Kim Hutchinson, Duke Environmental, Duke Energy  
 Evan Andrews, Duke CCP, Duke Energy  
 Will Harrison, Duke CCP, Duke Energy  
 Melanie Martin, Duke Environmental, Duke Energy

**STATUS OF PERMIT:**

Permit to Operate, Original, Issued: December 10, 1984  
 Closure Plan Approval Letter: December 7, 2007  
 Closure Construction, Completed: February 24, 2009  
**Closure Permit Issued: January 16, 2014**

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

None

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

1. The closed Pine Hall Ash Landfill was utilized primarily for the disposal of ash generated by the Belews Creek Steam Station and ceased receiving waste February, 2004.
2. Initial closure plan approval for the approximately 37.9 acre landfill was issued by the Solid Waste Section on December 7, 2007. Closure and cap construction was conducted April-December 2008. Additional approvals have been issued for landfill cap repairs/refit and assessment monitoring since closure was complete.
3. The groundwater/surface water monitoring report for the sampling event conducted October 20, 2014 was reviewed during the inspection.
4. All monitoring wells and surface sampling points were observed during this inspection. The following concerns were noted:

<b>8503-INDUS-1984: Pine Hall Road</b>			
Monitoring Well ID	Well Tag	Concrete Pad	Comments
MW-1	Yes	Yes	
MW-1D	Yes	Yes	
MW-2	Yes	Yes*	pad cracked, needs to be replace
MW-3	Yes	Yes	
MW-4	Yes	Yes	
MW-5	Yes	Yes	
MW-6	Yes	Yes	
MW-7	Yes	Yes	
MW-2-7	Yes	Yes	
MW-2-9	Yes	Yes	
OB-4	Yes*	Yes	well IDed, but no well construction info on tag
OB-5	Yes*	Yes	well IDed, but no well construction info on tag
OB-9	Yes	Yes	
SW-1A	NA	NA	needs surface water sample location sign
SW-2	NA	NA	needs surface water sample location sign

\*Action needed.

5. Permanent edge-of-waste markers are in place and being maintained.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

6. Facility access roads and perimeter roads are well maintained and of all-weather construction.
7. Sedimentation and erosion control features are in place and well maintained, no on-site or off-site erosion observed.
8. Established vegetative cover observed over the entire landfill. Periodic mowing of vegetative growth is conducted for the facility and landfill cap.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 919-707-8284

Environmental Senior Specialist

<b>Sent on:</b> May 22, 2015		Email: X		Hand delivery		US Mail		Certified No. [ ]
---------------------------------	--	-------------	--	---------------	--	---------	--	-------------------

- Copies:
- Ellen Lorscheider, Section Chief, Solid Waste Section
  - Ed Mussler, Permitting Branch Head, Solid Waste Section
  - Jason Watkins, Field Operations Branch Head, Solid Waste Section
  - Elizabeth Werner, Permitting Hydrogeologist, Solid Waste Section
  - Larry Frost, Engineering Project Manager, Solid Waste Section
  - Jessica Montie, Compliance Officer, Solid Waste Section