



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	COUNTY: Nash PERMIT NO.: 0056CCB FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: May 19, 2014 Date of Last Inspection: December 27, 2009

FACILITY NAME AND ADDRESS:

Brandywine Industrial Park
 NC Hwy 4
 Battleboro, North Carolina 27809

GPS COORDINATES: N: 36.04567 E: -077.76949

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Inez Grizelle G Holderness c/o Russell Holderness
 Telephone: 252 823 7295
 Email address: rusty@historictarboro.com
 Fax:

FACILITY CONTACT ADDRESS:

Inez & Grizelle B Holderness 403 Main St. Tarboro, North Carolina 27886	Russell Holderness P.O. Box 249 Tarboro, North Carolina 27886
---	---

PARTICIPANTS:

Ben Barnes, NCDENR Solid Waste Section
 Ellen Lorscheider, NCDENR, Solid Waste Section

STATUS OF PERMIT:

CCB Structural fill site, no permit required

PURPOSE OF SITE VISIT:

Inspection

STATUS OF PAST NOTED VIOLATIONS:

NONE

OBSERVED VIOLATIONS

NONE

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

- 1) The original submittal by ReUse Technology for a CCB structural fill site was dated May 4, 2001.
- 2) On July 5, 2001 the Division issued a letter to ReUse Technology indicating their submittal of May 4, 2001 and June 22, 2001 appears to meet the requirements of the .1700 Rules.
- 3) The site is owed by Inez and Gizzele Holderness, Rusty Holderness is the father of Inez and Gizzele Holderness.
- 4) The property has not been developed as of the date of this inspection.
- 5) Site is overgrown with pines at the time of this inspection.
- 6) There was some excavation of soil at the western area of the fill site prior to commencement of filling operations. ReUse Technologies claimed this was done to level the base of the fill area. A visit to the site during the fill operation revealed soil mottling in the area of excavation on the western side of the fill area.
- 7) There appears to be sufficient cover on the site.
- 8) The ash was transported from Cogentrix of North Carolina Southport Plant, P.O. Box 10836 Southport, NC 28461, Cogentrix of NC Roxboro Plant P.O. Box 1153 Roxboro, NC, 27573, and Cogentrix of Rocky Mount P.O. Box 370 Battleboro, NC 27809 and Burlington Worldwide, International Textile Group, 1001 Turnpike Rd. Raeford, NC 28376
- 9) A letter dated September 23, 2008 certifying completion of all fill activities and compliance with all requirements of Section .1700 was submitted to the Division by Full Circle Solutions formerly ReUse Technology. The letter did not list the book and page number of the recordation. Deed research revealed that the notice was recorded on October 16, 2009 in Book 86 page 85 in the Nash County Register of Deeds.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 252 236 4453 email: ben.barnes@ncdenr.gov

Ben Barnes
 Environmental Senior Specialist
 Regional Representative

Sent on: July 18, 2014		Email		Hand delivery	X	US Mail		Certified No. []
------------------------	--	-------	--	---------------	----------	---------	--	-------------------

Copies: Jason Watkins, Field Operations Branch Head
 Ellen Lorscheider, Special Waste Branch Head
 Dennis Shackelford District Supervisor
 Jessica Montie Compliance Officer

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3



Area of fill

Aerial of property



Views of the surface of the fill area.