



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>										
Lined MSWLF		LCID		YW		Transfer		Compost	SLAS	<b>COUNTY:</b> Nash <b>PERMIT NO.:</b> CCB0059 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

**Date of Site Inspection:** May 19, 2014      **Date of Last Inspection:** Initial inspection

**FACILITY NAME AND ADDRESS:**

Carolina Eagle Distributing Inc.  
 3231 N Wesleyan Blvd.  
 Rocky Mount, North Carolina 27804

**GPS COORDINATES:**      N: 36.01326    W: 77.76980

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name:                    Joe Saputo President    Russ Saputo Vice President  
 Telephone:            252977 2300  
 Email address:        [sales@carolinaeagle.com](mailto:sales@carolinaeagle.com)

**FACILITY CONTACT ADDRESS:**

Same as above

**PARTICIPANTS:**

Ellen Lorscheider, NCDENR SWS Special Waste Branch Head  
 Ben Barnes, NCDENR SWS

**STATUS OF PERMIT:**

CCB fill site. No permit required

**PURPOSE OF SITE VISIT:**

Inspection of closed and covered CCB structural fill site

**STATUS OF PAST NOTED VIOLATIONS:**

NONE

**OBSERVED VIOLATIONS**

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Site closed pre 1994 approximately 15000 tons/ 11,250 cubic yards applied.
2. On January 10, 1992 ReUse Technology Inc submitted a request to the Solid Waste Section for the use of CCB's as structural fill at Carolina Eagle Distributing Inc. in Rocky Mount. The property is located at 3231 N Wesleyan Blvd in Rocky Mount, NC a 7.32 acre tract parcel ID# 386210356803.
3. On February 10, 1992 the Solid Waste Section issued a letter indicating that the January 10, 1992 submittal by ReUse Technology met the previously agreed upon guidelines.
4. No exposed CCB's were observed.

Please contact me if you have any questions or concerns regarding this inspection report.

*Ben Barnes*

Phone: 252 236 4453 email: [ben.barnes@ncdenr.gov](mailto:ben.barnes@ncdenr.gov)

Environmental Senior Specialist  
***Regional Representative***

Sent on: July 18, 2014		Email		Hand delivery	X	US Mail		Certified No. [ ]
------------------------	--	-------	--	---------------	---	---------	--	-------------------

Copies: Jason Watkins, Field Operations Branch Head  
Ellen Lorscheider, Special Waste Branch Head  
Dennis Shackelford, Eastern District Supervisor  
Jessica Montie, Compliance Officer

FACILITY COMPLIANCE INSPECTION REPORT  
Division of Waste Management  
Solid Waste Section

Page 3 of 3




Aerial of property



building

View of the front of the

Fred Wood  
Re-use Technology  
Carolina Eagle, Inc.  
T.F.D.  
1/21/92



**LEGEND**

- PERMANENT SEEDING: SD-4
- GRADING: SD-17
- SU-6
- SU-14
- SU-19
- SD-18
- SD-1

30x36' = 1080 sq ft  
36x30' = 1080 sq ft  
156' x 17156' = 1749' x 4  
87' x 90' = 7830 sq ft

- F. MARSH BARNES -  
FRONTIER TRAILER ASSOC. INC.

EROSION & SEDIMENTATION CONTROL PLAN

U.S. HIGHWAY 301 BY-PASS

