



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID Notification	X	YW	Transfer	Compost	SLAS				COUNTY: Carteret NOTIFICATION NO.: LCIDN-N0096- FILE TYPE: COMPLIANCE
Closed MSWLF	HHW		White goods	Incin	T&P	FIRM				
CDLF	Tire T&P / Collection		Tire Monofill	Industrial Landfill	DEMO	SDTF				

Date of Site Inspection: 24 June 2015

Date of Last Inspection: 29 May 2015

FACILITY NAME AND ADDRESS:

Willis Construction & Grading Company LCID Landfill
 500 Miller Farm Road
 Morehead City, NC 28557

GPS COORDINATES: N: 34.74711 E: 76.79491

FACILITY CONTACT NAME AND PHONE NUMBER:

Billy Miller
 252.726.9429

FACILITY CONTACT ADDRESS:

Miller Construction & Landscaping
 205 Miller Farm Road
 Morehead City, NC 28557

Attn. Billy Miller

E-mail: kathleentaylor217@gmail.com

PARTICIPANTS:

Kathleen Taylor; Miller Construction & Landscaping
 Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification

PURPOSE OF SITE VISIT:

Comprehensive Facility Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

No violations were observed during this Facility Compliance Inspection; please see the ADDITIONAL COMMENTS section below.

ADDITIONAL COMMENTS:

- 1) This Facility is a Land-Clearing and Inert Debris Landfill Notification.
- 2) This facility is recorded with the Carteret County Register of Deeds at: Book #1165; Page #354.
- 3) This Facility is permitted to receive for disposal:
 - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
 - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
 - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
 - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) This Facility is monitored by a 24 hour security camera at the Facility entrance.
- 6) This Facility is secured by a locked gate at the Facility entrance and has controlled access for safety.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0096-20150624INSP

Page 2 of 3

- 7) Proper signage is posted at the Facility entrance stating the Facility emergency contact number and types of waste accepted.
- 8) The access road to the Facility is of all-weather construction and is being managed properly at this time.
- 9) No burning waste was visible and no smoke was observed emanating from the Facility during this Facility Compliance Inspection.
- 10) The recently burned areas of the landfill have been covered and compacted.
- 11) The outside slopes appear to be properly graded but, due to the recent fire event, are lacking sufficient cover. *As soon as practical please ensure that all slopes are seeded and mulched to establish a groundcover suitable to prevent erosion of the landfill cap system.



- 12) The operator has resumed waste disposal activities at this site. The waste type being disposed is LCID waste only; no unacceptable waste streams were noted during this Facility Compliance Inspection.



- 13) *Please continue to ensure that all waste is covered monthly or when the active working faces reaches 1 acre in size, whichever occurs first.
- 14) The perimeter of the landfill has been staked to identify the landfill footprint.
- 15) The Facility operator is currently screening and stockpiling soil in an area adjacent to the landfill for use in cover and grading.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0096-20150624INSP

Page 3 of 3



- 16) No violations were observed during this Facility Compliance Inspection.
- 17) *Corrective actions are required as a result of this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>1 July 2015</u> by	X	Electronic delivery		US Mail		Certified No. []
---	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
 Jessica Montie; Chief Compliance Officer/SWS: jessica.montie@ncdenr.gov

C: \2015\Carteret\Notifications\N0096\Inspections\N0096-20150624INSP
 NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>



Go Green! Thank you for helping NCDENR be environmentally responsible.