



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID Notification	X	YW	Transfer	Compost	SLAS	COUNTY: Carteret NOTIFICATION NO.: N0218 FILE TYPE: COMPLIANCE		
Closed MSWLF	HHW		White goods	Incin	T&P	FIRM			
CDFL	Tire T&P / Collection		Tire Monofill	Industrial Landfill	DEMO	SDTF			

Date of Site Inspection: 16 July 2014

Date of Last Inspection: 8 January 2014

FACILITY NAME AND ADDRESS:

Larry Styron LCID Landfill
 Herring-Smith Road
 Newport, NC 28570

GPS COORDINATES: N: 34.76937 E: 76.84432

FACILITY CONTACT NAME AND PHONE NUMBER:

Tina Sibley
 252.422.8404

FACILITY CONTACT ADDRESS:

Styron Properties
 PO Box 1599
 Morehead City, NC 28570
 E-mail: tsibley@ec.rr.com

PARTICIPANTS:

Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification for a site less than 2 acres in size.

PURPOSE OF SITE VISIT:

Comprehensive Facility Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

No violations were observed during this Facility Compliance Inspection. Please see ADDITIONAL COMMENTS section below.

ADDITIONAL COMMENTS:

- 1) This Facility is a Land-Clearing and Inert Debris (LCID) Landfill Notification.
- 2) This Facility is recorded with the Carteret County Register of Deeds at: Book 913; Page 399.
- 3) This Facility is permitted to receive for disposal:
 - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
 - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
 - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
 - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) This Facility is monitored by a 24 hour security camera placed adjacent the facility access road.
- 6) This Facility is secured by a locked gate at the facility entrance and has controlled access for safety. The gate was closed and no attendant was on site during this Facility Compliance Inspection.
- 7) The access road to the Facility is being managed properly at this time.
- 8) The Facility has been capped and is no longer receiving waste. However, the facility operator wishes to maintain active status for possible future use.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0218-20140716INSP

Page 2 of 3

- 9) The Facility sign has been damaged. *Please re-post proper signage at the facility entrance stating the facility emergency contact number and types of waste accepted.
- 10) A cover crop of native warm season grasses and coppice-type cover has been established throughout the facility. Some brush and woody vegetation has been established on portions of the landfill sideslopes. *Plans need to be underway for the mowing of the landfill cover crop and removal of the brush and other woody type vegetation. After mowing, please ensure that all landfill sideslopes have a groundcover established suitable to prevent erosion of your landfill cap system.



- 11) Soil has been stockpiled on-site for use in cover maintenance in an area adjacent to the landfill access ramp.



- 12) The landfill disposal footprint markers have been knocked down and/or removed. *Please re-install the landfill footprint markers to delineate the waste disposal boundaries.
- 13) The access around the toe of the northern and eastern sideslopes of the landfill has overgrown with brush and woody vegetation. *Please mow the access around the perimeter of the landfill for more efficient Facility Inspections and maintenance operations.
- 14) *Corrective actions are required as a result of this Facility Compliance Inspection Report.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

REGIONAL REPRESENTATIVE

Delivered on : <u>22 July 2014</u> by:	X	Electronic delivery		US Mail		Certified No. []
---	---	---------------------	--	---------	--	-------------------

CC: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
 Jessica Montie; Chief Compliance Officer/SWS: jessica.montie@ncdenr.gov

C: \2014\Carteret\Notifications\N0218\Inspections\N0218-20140716INSP
 NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0218-20140716INSP

Page 3 of 3

One
North Carolina
Naturally

 Go Green! Thank you for helping NCDENR be environmentally responsible.