



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID Notification	X	YW	Transfer	Compost	SLAS	COUNTY: Carteret NOTIFICATION NO.: N0620 FILE TYPE: COMPLIANCE		
Closed MSWLF	HHW		White goods	Incin	T&P	FIRM			
CDFL	Tire T&P / Collection		Tire Monofill	Industrial Landfill	DEMO	SDTF			

Date of Inspection: 26 August 2014

Date of Last Inspection: 29 August 2012

FACILITY NAME AND ADDRESS:

Dixon Pit LCID Landfill
 2628 Hwy 24
 Newport, NC 28570

GPS COORDINATES: N: 34.73488 E: 76.92395

FACILITY CONTACT NAME AND PHONE NUMBER:

Curtis S Dixon
 252.247.2643

FACILITY CONTACT ADDRESS:

2628 Hwy 24
 Newport, NC 28570
 E-mail: the2dixons@earthlink.net

PARTICIPANTS:

Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification

PURPOSE OF SITE VISIT:

Comprehensive Facility Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

No violations were observed during this Facility Compliance Inspection; please see the ADDITIONAL COMMENTS section below.

ADDITIONAL COMMENTS:

- 1) This Facility is a Land-Clearing and Inert Debris Landfill Notification under two acres in size.
- 2) This Facility is recorded with the Carteret County Register of Deeds at: Book 1040; Page 32.
- 3) This Facility is permitted to receive for disposal:
 - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
 - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
 - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
 - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) This Facility is secured by a locked gate at the Facility entrance and has controlled access for safety. The gate was closed and locked and no attendant was on site during this Facility Compliance Inspection.
- 5) Proper signage is posted at the facility entrance stating the Facility emergency contact number.
- 6) The Facility access road is of all-weather construction and is being managed properly at this time.
- 7) Soil has been stockpiled for use as cover adjacent to the landfill access road.
- 8) The active disposal area was reviewed. The active disposal area was compact and no unpermitted wastes were observed during this Facility compliance inspection.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0620-20140826INSP

Page 2 of 2

- 9) Overall, this Facility has a well-established cover crop of native warm season grasses and coppice-type cover.
- 10) Portions of the Facility have recently been mowed.



- 11) *The Facility sideslopes need to be mowed and maintained to prevent the growth of brush and woody vegetation which can shade out and otherwise inhibit the growth of the desired grass cover crop.



- 12) *Corrective actions are required as a result of this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Ray Williams

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>28 August 2014</u> by	X	Electronic delivery		US Mail		Certified No. []
--	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
 Jessica Montie; Chief Compliance Officer/SWS: jessica.montie@ncdenr.gov

C: \2014\Carteret\Notifications\N0620\Inspections\N0620-20140826INSP
 NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

