



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:										
Lined MSWLF		LCID Notification	X	YW		Transfer		Compost	SLAS	COUNTY: Carteret NOTIFICATION NO.: LCIDN-N0655- FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

Date of Site Inspection: 20 November 2014 **Date of Last Inspection:** 18 June 2014

FACILITY NAME AND ADDRESS:

Anna Wink LCID Landfill
 Anna Wink Road
 Newport, NC 28570

GPS COORDINATES: N: 34.77667 E: -076.94352

FACILITY CONTACT NAME AND PHONE NUMBER:

Tina Sibley
 252.422.8404

FACILITY CONTACT ADDRESS:

Styron Properties
 PO Box 1599
 Morehead City, NC 28570
 E-mail: tsibley@ec.rr.com

PARTICIPANTS:

Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification

PURPOSE OF SITE VISIT:

Comprehensive Facility Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

No violations were observed during this Facility Compliance Inspection; *please see* ADDITIONAL COMMENTS section below.

ADDITIONAL COMMENTS:

- 1) This facility is a Land-Clearing and Inert Debris Landfill Notification.
- 2) This facility is recorded with the Carteret County Register of Deeds at: Book 913; Page 399.
- 3) This facility is permitted to receive for disposal:
 - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
 - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
 - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
 - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) The access road to the Facility is being managed properly at this time.
- 6) This Facility is secured by a locked cable at the Facility entrance and has controlled access for safety.
- 7) Proper signage has been posted at the Facility entrance.
- 8) No off-site erosion was noted during this Facility Compliance Inspection.
- 9) The perimeter road has been cleared to provide access around the toe of the landfill.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0655-20141120INSP

Page 2 of 2

- 10) The landfill working face has been covered and graded and no exposed waste was observed during this Facility Compliance Inspection.
- 11) The landfill side slopes have been covered and graded to promote positive drainage of surface waters away from the landfill.
- 12) The landfill has a well-established cover crop of mixed native warm season grasses.
- 13) Soil has been stockpiled on the top lift of the landfill for use as cover.
- 14) No new disposal activity has occurred since the last Facility Compliance Inspection.
- 15) No violations were observed during this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>21 November 2014</u> by	X	Electronic delivery		US Mail		Certified No. []
--------------------------------------------------	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
Jessica Montie; Chief Compliance Officer/SWS: jessica.montie@ncdenr.gov

C: \2014\Carteret\Notifications\N0655\Inspections\N0655-20141120INSP
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

 Go Green! Thank you for helping NCDENR be environmentally responsible.

One
North Carolina
Naturally