



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID Notification	<b>X</b>	YW		Transfer		Compost		SLAS		<b>COUNTY: Carteret</b> <b>NOTIFICATION NO.: N1070</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Inspection:** 5 August 2014

**Date of Last Inspection:** 12 September 2013

**FACILITY NAME AND ADDRESS:**

Bennett Neck Road Mine LCID Landfill  
 382 Bennett Neck Road  
 Grantsboro, NC 28529

**GPS COORDINATES:** **N:** 35.02632 **E:** -76.88377

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Jesse B Cahoon  
 252.249.1617

**FACILITY CONTACT ADDRESS:**

Bobby Cahoon Marine Construction, Inc  
 6003 Neuse Road  
 Grantsboro, NC 28529  
 E-mail: [bobbycagoonconstruction@yahoo.com](mailto:bobbycagoonconstruction@yahoo.com)

**PARTICIPANTS:**

Ray Williams; NCDENR-Solid Waste

**STATUS OF PERMIT:**

Active: Landclearing and Inert Debris (LCID) Landfill Notification

**PURPOSE OF SITE VISIT:**

Comprehensive Facility Compliance Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

None applicable

**OBSERVED VIOLATIONS:**

No violations were observed during this Facility Compliance Inspection; please see ADDITIONAL COMMENTS section below.

**ADDITIONAL COMMENTS:**

- 1) This facility is a Land-Clearing and Inert Debris Landfill Notification.
- 2) This facility is recorded with the Pamlico County Register of Deeds at: Book 583; Page 885.
- 3) This facility is permitted to receive for disposal:
  - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
  - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
  - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
  - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) The access road to the Facility is being managed properly at this time.
- 6) This Facility is secured by a locked gate at the Facility entrance and has controlled access for safety. The gate was closed and locked upon my arrival.
- 7) Proper signage has not been posted at the Facility entrance. \*As per our conversation, please install proper signage at the Facility entrance stating the Facility Name and Emergency Contact number.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

N1070-20140805INSP

Page 2 of 2

- 8) Landfill disposal footprint markers have not been installed. \*As per our conversation, please install permanent markers around the perimeter of the landfill delineating the permitted disposal area.
- 9) The landfill side slopes have been covered and graded to promote positive drainage of surface waters away from the landfill.
- 10) The landfill working face has been covered and graded and minimal exposed waste was observed during this Facility Compliance Inspection.



- 11) Soil has been stockpiled at the landfill for use as cover.
- 12) No off-site erosion was noted during this Facility Compliance Inspection.
- 13) No violations were observed during this Facility Compliance Inspection.
- 14) \*Corrective actions are needed as a result of this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: [ray.williams@ncdenr.gov](mailto:ray.williams@ncdenr.gov)

***Regional Representative***

<b>Delivered on : <u>8 August 2014</u> by</b>	X	Electronic delivery		US Mail		Certified No. [ ]
---	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: [dennis.shackelford@ncdenr.gov](mailto:dennis.shackelford@ncdenr.gov)  
Jessica Montie; Chief Compliance Officer/SWS: [jessica.montie@ncdenr.gov](mailto:jessica.montie@ncdenr.gov)

C: \2014\Pamlico\Notifications\N1070\Inspections\N1070-20140805INSP  
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

Go Green! Thank you for helping NCDENR be environmentally responsible.

One  
North Carolina  
*Naturally*