



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:										
Lined MSWLF		LCID	X	YW		Transfer		Compost	SLAS	COUNTY: Caswell PERMIT NO.: N0151 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

Date of Site Inspection: September 2, 2015

Date of Last Inspection: July 17, 2013

FACILITY NAME AND ADDRESS:

Doggett LCID Landfill
 Cherry Grove Road
 Reidsville, NC 27320

GPS COORDINATES: N: 36.30309 E: -79.48024

FACILITY CONTACT NAME AND PHONE NUMBER:

Mark Doggett, President - Doggett Construction Company, Inc.
 w. 336-643-4103/9437
 c. 336-681-3333
dccmarkd@gmail.com

FACILITY CONTACT ADDRESS:

Doggett Construction Company, Inc.
 Mark Doggett - President
 2124 Scalesville Road
 Summerfield, NC 27358

PARTICIPANTS

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)
 Mark Doggett, President - Doggett Construction Company, Inc.

STATUS OF PERMIT:

Land Clearing and Inert Debris Landfill Notification recorded with the Caswell County Register of Deeds November 16, 1994
 Land Clearing and Inert Debris Landfill Notification approval letter dated November 28, 1994 issued by the SWS to Truman Doggett.
 Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

PURPOSE OF SITE VISIT:

Comprehensive Inspection (to ensure that the notified land clearing and inert debris (LCID) landfill is in compliance with 15A North Carolina Administrative Code (NCAC) 13B .0563, .0564, and .0566)

STATUS OF PAST NOTED VIOLATIONS

None

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 3

OBSERVED VIOLATIONS

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

On September 2, 2015, John Patrone met with Mark Doggett to conduct a comprehensive inspection of the Doggett Land Clearing and Inert Debris Landfill on Cherry Grove Road in Reidsville, Caswell County.

1. The facility is a land clearing and inert debris (LCID) landfill located on an undeveloped parcel of land.
2. Access to the site is via a gravel/dirt road on the left immediately after mailbox no. 8225. Boone Road intersects Cherry Grove Road prior to facility entrance.
3. The facility is not open to the public.
4. Mr. Doggett stated that the facility is used by the Doggett Construction Company, Inc. and that it is used infrequently/when working in the area.
5. The LCID landfill is ~ 1 acre.
6. The LCID landfill is covered with soil.
7. Mr. Doggett stated that additional grading will occur and grass seed will be sown.
8. Soil will be stockpiled on site from construction projects for future use.
9. Per 15A NCAC 13B .0566(3), "Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells."
10. Per 15A NCAC 13B .0566(4), "Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first."
11. Side slopes should be graded such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed.
12. Access roads are of all-weather construction.
13. The landfill area is fenced and locked.
14. The facility has a proper sign.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 336-776-9673

John Patrone, Environmental Senior Specialist
 Division of Waste Management, NCDENR

Sent on: <u>September 3, 2015</u>	X	Email		Hand delivery		US Mail	Certified No. []
-----------------------------------	---	-------	--	---------------	--	---------	-------------------

Electronic Copies: Deb Aja, Western District Supervisor - SWS
 Jessica Montie, Compliance Officer - SWS

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3

Digital pictures taken September 2, 2015
by John Patrone, DWM-SWS

Facility sign, next to entrance gate



LCID landfill area – right side



LCID landfill area– left side



LCID landfill area – center

