



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		NLCID	<b>X</b>	YW		Transfer		Compost		SLAS		<b>COUNTY: LINCOLN</b> <b>PERMIT NO.: N 0433</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection: 05/28/15**

**Date of Last Inspection: Unknown**

**FACILITY NAME AND ADDRESS:**

Goodson Land Clearing and Inert Debris Site  
 6790 Kidville Rd. (SR-1381)  
 Denver, NC 28031

**GPS COORDINATES:** N: 35.49874° W 81.04585°

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Sam Goodson  
 Telephone: 704-763-6068

**FACILITY CONTACT ADDRESS:**

6790 Kidville Rd.  
 Denver, NC 28031

**PARTICIPANTS:**

Bill Wagner, NCDENR – Solid Waste Section

**STATUS OF PERMIT:**

Notification approved October 19, 1998

**PURPOSE OF SITE VISIT:**

Comprehensive Compliance Inspection

**STATUS OF PAST NOTED VIOLATIONS:**


None

**OBSERVED VIOLATIONS:**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**



**Figure 1: NLCID 0433 – 6790 Kidville Rd., Denver, NC**

**ADDITIONAL COMMENTS**

1. The original notification lists Mrs. Kathleen Goodson as the land owner. The Lincoln County Register of Deeds lists Mr. Samuel Thomas Goodson as the current owner of Parcel 34700.
2. The facility appears to be less than two acres.
3. The required buffers from the limits of waste appear to be properly maintained.
4. Access to the site is controlled by a gate and a small shack for a site attendant. (Photos #1 - #2)



1. Looking from Kidville Rd. at the gated entrance to the site.



2. Secondary sign at the gated entrance to the site.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3



3. Looking SE down perimeter access road at truck actively dumping land clearing debris.

4. Looking down access road into the facility.

5. The facility was actively receiving wastes during the inspection. (Photo #3)

6. No prohibited wastes were observed.

Please contact me if you have any questions or concerns regarding this inspection report.

\_\_\_\_\_  
Bill Wagner  
Environmental Senior Specialist  
*Regional Representative*

Phone: 828-296-4705

Sent on: 5/29/15		Email:		US Mail:		Certified No. [ ]
------------------	--	--------	--	----------	--	-------------------

ec: Deb Aja, Western District Supervisor – Solid Waste Section  
Jessica Montie, Compliance Officer – Solid Waste Section