



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Brunswick PERMIT NO.: SLAS-10-13 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 10-17-13

Date of Last Inspection: 3-27-13

FACILITY NAME AND ADDRESS:

Robinson's Septic Tank Cleaning
 904 Sabbath Home Rd SW
 Supply, NC 28462

GPS COORDINATES: N: 34.00519° E: -78.21545°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Jimmy Robinson
 Telephone: 910-842-6606
 Email address:
 Fax:

FACILITY CONTACT ADDRESS:

Same as Above

PARTICIPANTS:

Will Burke, Environmental Senior Specialist

STATUS OF PERMIT:

Active Expires 11-1-15

PURPOSE OF SITE VISIT:

Routine, Audit

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1) Winter crop has been drilled.
- 2) Signage was adequate.
- 3) **Make sure field markers are present and easy to identify. Also, make sure applications are taking place inside these marked areas correctly. Please repair any broken markers.**
- 4) Minimal objectionable odors were present, no vectors were noted.
- 5) All setbacks appear to have been followed and maintained.
- 6) Access road was acceptable.
- 7) In the spring work on Bermuda coverage.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 796-7397

Will Burke
Regional Representative

Sent on: 1-15-14		Email		Hand delivery	X	US Mail		Certified No. []
------------------	--	-------	--	---------------	---	---------	--	-------------------