



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Site visit conducted to evaluate field for suitability as a septage land application site. Field was previously permitted to Mr. Sam Carteret under permit #SLAS-10-18. Permit #SLAS-10-18 was closed out on 3/4/2008. From 4/1/09 to 2/8/13, field was permitted by Division of Water Quality to receive bio residuals.
2. Site has an established bermudagrass stand and had been overseeded with a small grain for a winter crop.
3. Ms. Wylie and I established the setbacks to residences, wells, property lines, and surface waters. Orange flags were placed to mark the area that could be permitted for a septage land application site. I will need to review some of the setbacks to the surface waters with my supervisors. Once confirmed, permanent markers will need to be placed at the flags.
4. Field was mapped with a Trimble GPS unit. Also, pictures were taken of the site.



Picture taken looking west across field to pond.



Picture taken looking east towards the SDTF.

Please contact me if you have any questions or concerns regarding this inspection report.

*Chester R. Cobb*

Chester R. Cobb, Soil Scientist  
 Division of Waste Management, NCDENR  
*Regional Representative*

Phone: (919) 707-8283.

Sent on: 7/8/14		Email		Hand delivery	X	US Mail		Certified No. [ ]
-----------------	--	-------	--	---------------	---	---------	--	-------------------