



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Camden PERMIT NO.: SLAS-15-02 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 7/9/2014 **Date of Last Inspection:** 4/7/2014

FACILITY NAME AND ADDRESS:

*Joseph Russell
 Albemarle Septic Services
 134 Belcross Rd.
 Camden, NC 27921*

GPS COORDINATES:

N: 36.37113

E: -76.17317

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Mike Russell*
Telephone: *252-202-9969*
Email address: *albsepticsservice@centurylink.net*
Fax: *252-333-5008*

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: *Chester Cobb and Mike Russell*

STATUS OF PERMIT: *Active*

EXPIRES: *7/16/2014*

PURPOSE OF SITE VISIT: *Routine*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the inspection conducted on 4-7-14.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Signage present as you get to Field A.
2. Path to site was in good shape.
3. All field markers were present.
4. All discharges appeared to be within the permitted boundaries of the fields.
5. No thick applications or spot dumps noticed.
6. Mike said that he had broadcasted Cheyene Bermudagrass seeds over the fields earlier this year. He said that last year he had drilled the seeds into the bermudagrass sod. We talked some about weed control. He is going to get a local farmer to spray for nutsedge control. Also, some broadleaf weed control is needed in Field B. The eastern side of Field B has a lot of the broadleaf weed, buckhorn plantain.
7. No application at time of inspection. pH not checked.
8. No objectionable odors were noticed today.
9. No change noticed with any setbacks.
10. Records have been sent in along with an application for permit renewal.
11. Some weed control is needed for nutsedge and buckhorn plantain. Mike is working with a local farmer on weed control.

Please contact me if you have any questions or concerns regarding this inspection report.



Chester R. Cobb, Soil Scientist
Division of Waste Management, NCDENR
Regional Representative

Phone: (919) 707-8283

Sent on: 12/17/14		Email		Hand delivery	X	US Mail		Certified No. []
-------------------	--	-------	--	---------------	---	---------	--	-------------------