



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Camden</b> <b>PERMIT NO.: SLAS-15-4</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection: 5-22-13.**

**Date of Last Inspection: 11-20-12**

**FACILITY NAME AND ADDRESS:**

CS Hines, Inc  
 1828 Mount Pleasant Rd  
 Chesapeake, VA 23322

**GPS COORDINATES:** N: 36.33687° W: -76.05817°

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: CS Hines  
 Telephone: 757-482-7001  
 Email address:  
 Fax:

**FACILITY CONTACT ADDRESS:**

Same

**PARTICIPANTS:**

Will Burke, Environmental Senior Specialist

**STATUS OF PERMIT:**

**Active**

**PURPOSE OF SITE VISIT:**

Routine, Audit

**OBSERVED VIOLATIONS**

1.n/a

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Please work on weed control in the application fields.
2. Access road was in good shape.
3. No serious odors or vectors were noticed during this inspection
4. Appropriate signage was up and easy to read.
5. Field border markers were up and easy to identify.
6. Applications appear to have been performed in a professional and responsible manner.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 796-7397

---

Will Burke  
***Regional Representative***

Sent on: 5-30-13		Email		Hand delivery		US Mail		Certified No. [ ]
------------------	--	-------	--	---------------	--	---------	--	-------------------