



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Carteret</b> <b>PERMIT NO.: SLAS-16-08</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection: 08-24-2015**

**Date of Last Inspection: 05-06-2015**

**FACILITY NAME AND ADDRESS:**

Garner Construction Company  
 5970 Hwy. 70  
 Newport, NC 28570

**GPS COORDINATES:** N: 34.80898 W: -76.92642

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Keith Garner  
 Telephone: 252-223-4019

**FACILITY CONTACT ADDRESS:**

Same as above

**PARTICIPANTS:**

Morgan Garner – Owner  
 John College - DWM

**STATUS OF PERMIT:**

Active – expires 01-13-2017

**PURPOSE OF SITE VISIT:**

Routine

**STATUS OF PAST NOTED VIOLATIONS:**

None

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2



**ADDITIONAL COMMENTS**

- 1 – Site has proper signage.
- 2 – Good access road.
- 3 – Markers are up and appear to be accurate.
- 4 – Septage discharges all appear to be within permitted boundaries.
- 5 – Applications appear to be in compliance.
- 6 – Crops are doing fair. Mr. Garner is using a herbicide to improve Bermuda stand.
- 7 – No objectionable odors noted.
- 8 – Setbacks appear to be in compliance.
- 9 – Soil Samples taken.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 910-796-7397

Environmental Senior Specialist  
*Regional Representative*

Sent on: 08-28-2015	Email	Hand delivery	<input checked="" type="checkbox"/>	US Mail	Certified No. [ ]
---------------------	-------	---------------	-------------------------------------	---------	-------------------