



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: CLEVELAND PERMIT NO.: SDTF 23-11 FILE TYPE: COMPLIANCE
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

Date of Site Inspection: 10/09/14

Date of Last Inspection:

FACILITY NAME AND ADDRESS:

Rhea's Backhoe & Septic Tank Service

GPS COORDINATES:

N: 35.24197 W: 81.43771

FACILITY CONTACT NAME AND PHONE NUMBER:

Trent Rhea, owner/operator
 (704) 739-5849

FACILITY CONTACT ADDRESS:

5030 Harmon Road
 Kings Mountain, NC 28086

PARTICIPANTS:

Bill Wagner, NCDENR Solid Waste Section

STATUS OF PERMIT:

Issued: 07/02/14
 Expires: 12/03/18

PURPOSE OF SITE VISIT:

Comprehensive Inspection and collection of one soil sample.

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

None.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS:




Figure 1: Rhea's Septage Land Application Site (SLAS) 23-11
1140 Long Branch Rd. (SR-2238), Cleveland County, Grover, NC

2. The site consists of one 2.5-acre land application field located at the end of an un-named dirt road (south of *Southern Import Auto Parts*) off the west side of Long Branch Road (SR-2238).
3. The site (Parcel #10140) is owned by Donald Whitworth, 1132 Long Branch Rd., Grover, NC 28073
4. **The access road was passable, but needs improvement to address existing ruts and erosion.** (Photo #1)



2. Significant ruts / erosion on the western section of the access road that is in need of repair.



1. Small red "flag" (typical) used to mark the "100-ft. buffer region" of the application field.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3



3. Looking SW across the land application field.
 (Note the approximate location of the “100-foot
 buffer line” on the left.)

5. The “100-foot buffer area” is marked with multiple small red flags. (Photo #2)
6. Permitted setbacks and buffers appeared to be maintained.
7. Disposal area boundaries were apparent and septage discharges were made within the disposal area boundary.
8. The facility it permitted to use both Septage Detention & Treatment Facility (SDTF) #23-20 and the Shelby, NC Waste Water Treatment Plant as alternative disposal sites.
9. One soil sample was collected for analysis for the possible presence of heavy metals by the NCDA&CS Agronomic Soil Testing Section.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 828-296-4705

Bill Wagner
 Environmental Senior Specialist
Regional Representative

Sent on: 10/10/14		Email		Hand delivery	X	US Mail	Certified No. []
--------------------------	--	-------	--	------------------	----------	--------------------	-------------------

ec: Tony Gallagher, Branch Manager - Compost & Land Application Branch
 Deb Aja, Western District Supervisor – Solid Waste Section
 Liz Patterson, Compost & Land Application Branch
 Connie Wylie, Soil Scientist - Compost & Land Application Branch