



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Columbus</b> <b>PERMIT NO.: SLAS-24-07</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection: 10-07-2014**

**Date of Last Inspection: 11-04-2013**

**FACILITY NAME AND ADDRESS:**

Rudolf Inman Septic Tank Service  
 Ben Harrelson  
 5454 James B. White Hwy. S  
 Whiteville, NC 28472

**GPS COORDINATES:** N: 34.24136                      E: -78.70826

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Ben Harrelson  
 Telephone: 910-642-7431  
 Email address: N/A

**FACILITY CONTACT ADDRESS:**

Same as above

**PARTICIPANTS:**

Ben Harrelson & John College ( DWM )

**STATUS OF PERMIT:**

Active – Expires 01-01-2015

**PURPOSE OF SITE VISIT:**

Routine

**STATUS OF PAST NOTED VIOLATIONS:**

None

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2



**ADDITIONAL COMMENTS**

- 1 – Proper signage.
- 2 – Good access road.
- 3 – Markers appear to be in compliance.
- 4 – Discharges & applications appear to be in compliance.
- 5 – Great stand of Bermuda.
- 6 – No objectionable odors noted.
- 7 – Setbacks appear to be in compliance.
- 8 – Soil Samples taken.

Please contact me if you have any questions or concerns regarding this inspection report.

*John Colledge*

---

Phone: 910-796-7397

Environmental Senior Specialist  
***Regional Representative***

Sent on: 10-10-2014		Email		Hand delivery	<b>X</b>	US Mail	Certified No. [ ]
---------------------	--	-------	--	---------------	----------	---------	-------------------

Copies: