



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	<b>X</b>	<b>COUNTY: Currituck</b> <b>PERMIT NO.: SLAS-27-08</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

**Date of Site Inspection:** 4/7/2014    **Date of Last Inspection:** 11/20/2013

**FACILITY NAME AND ADDRESS:**

*Charles E. Younts Jr.*  
*Eddie Younts Septic Service*  
*77 64 Caratoke Hwy*  
*Powells Point, NC 27966*

**GPS COORDINATES:**

**N:** 36.15694

**E:** -75.84139

**FACILITY CONTACT NAME AND PHONE NUMBER:**

**Name:** *Eddie Younts*  
**Telephone:** *252-491-8445*  
**Email address:**  
**Fax:** *252-491-8240*

**FACILITY CONTACT ADDRESS:**

*Same as above*

**PARTICIPANTS:**    *Chester Cobb*

**STATUS OF PERMIT:** *Expired*

**EXPIRES:**    *12/22/2013*

**PURPOSE OF SITE VISIT:** *Routine*

**STATUS OF PAST NOTED VIOLATIONS:**

No violation noted on the previous inspection.

**OBSERVED VIOLATIONS:**

1) There was septage debris by the concrete tank next to Field 1. This is a violation of Rule .0838(a)(12) that states "All septage discharges, including aerial drift from discharges, shall be made within the permitted boundaries of the land application site." The septage debris by the concrete tank is not on the septage land application site. The only place where septage can be on the ground is on your permitted land application site. Need to clean up the septage debris from around the concrete tank and dispose of properly.

*The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.*

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Signage present as you enter site.
2. Access road in good shape.
3. All markers were present.
4. Minus the septage debris outside of the concrete tank, no septage discharges noticed outside of the permitted boundaries of the fields. Need to clean up the septage debris from around the concrete tank and dispose of properly. See pictures below.
5. No spot dumps or thick applications noticed today.
6. Good coverage of the small grain on all the fields.
7. No application at time of inspection. pH not checked.
8. No objectionable odors noticed today.
9. No change observed that would affect setback distances.
10. Application for permit renewal has been received. Records under review.
11. Septage debris needs to be cleaned up from around the concrete tank. Also, septage cannot be stored within the concrete tank.



Septage debris by the concrete tank in front of Field 1.



Septage debris on the ground by the concrete tank.

Please contact me if you have any questions or concerns regarding this inspection report.

*Chester R. Cobb*

Chester R. Cobb, Soil Scientist  
 Division of Waste Management, NCDENR  
*Regional Representative*

Phone: (919) 707-8283

Sent on: 12/17/14		Email		Hand delivery	X	US Mail	Certified No. [ ]
-------------------	--	-------	--	---------------	---	---------	-------------------