



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Duplin PERMIT NO.: SLAS-31-11 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 03-26-2015

Date of Last Inspection: 10-27-2014

FACILITY NAME AND ADDRESS:

Hall's Septic Tank Cleaning Service
 297 Durwood Evans Rd.
 Beulaville, NC 28518

GPS COORDINATES: N:34.88464 E: -77.78972

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Emmett G. Hall
 Telephone: 910-298-5750

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Emmett Hall
 John College - DWM

STATUS OF PERMIT:

Active – expires 02-04-2017

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

None

OBSERVED VIOLATIONS

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1 – Has signage. Sign is not 2 ft. x 2 ft. **Please replace with 2 ft. x 2 ft. sign, with SEPTAGE LAND APPLICATION SITE AND NO TRESPASSING** as stated in **15A NCAC 13B .0838 – 2 (Management of Land Application Sites.)** Thank you.



2 – Access road is in good condition.

3 – Field #1 disposal boundaries markers are good. Field #2 is missing front (East) disposal boundary marker. Please replace.

4 – Septage discharges appear be within permitted boundaries.

5 – Both Fescue fields may need to be re-seeded in the fall of 2015. Please contact your Duplin Co. Cooperative Extension Agent for help. Amanda Hatcher – Director, 910-296-2143.



6 – No objectionable odors noted.

7 – Records appear to be properly recorded.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 910-796-7397

Environmental Senior Specialist
Regional Representative

Sent on: 04-02-2015		Email		Hand delivery	X	US Mail		Certified No. []
---------------------	--	-------	--	---------------	---	---------	--	-------------------