



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Duplin PERMIT NO.: SLAS-31-13 FILE TYPE: COMPLIANCE
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDFL	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

Date of Site Inspection: 2-21-13

Date of Last Inspection: August 2012

FACILITY NAME AND ADDRESS:

Kenneth W. Register, JR
 630 Penny Branch Rd
 Warsaw NC, 28398

GPS COORDINATES: N: 34.9136° E: -78.0633

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Kenneth Register, Jr
 Telephone: 910-293-4022
 Email address:
 Fax:

FACILITY CONTACT ADDRESS:

Same as Above

PARTICIPANTS:

Will Burke, Environmental Senior Specialist

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine, Audit

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1) Winter crop appear to be strong.
- 2) Applications appear to have been done in a manner to prevent over-application and ponding.
- 3) No objectionable odors or vectors were noticed during the inspection.
- 4) Access road was in good shape.
- 5) Markers were up and easy to identify.
- 6) Please remove cut and baled hay from field borders as soon as possible.

Please contact me if you have any questions or concerns regarding this inspection report.



Will Burke

Regional Representative

Phone: (910) 796-7397

Sent on: 3-18-13		Email		Hand delivery	X	US Mail	Certified No. []
------------------	--	-------	--	---------------	---	---------	-------------------