



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	<b>X</b>	<b>COUNTY: Duplin</b> <b>PERMIT NO.: SLAS-31-14</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDFL	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

**Date of Site Inspection: 11-5-13**

**Date of Last Inspection: 3-21-13**

**FACILITY NAME AND ADDRESS:**

Dobson Septic Tank Pumping Service  
 278 Graham Dobson Rd.  
 Magnolia NC 28453

**GPS COORDINATES: N: 34.91684° E: -77.94743**

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: James Dobson  
 Telephone: 910-296-4620  
 Email address:  
 Fax:

**FACILITY CONTACT ADDRESS:**

Will Burke, Environmental Senior Specialist

**PARTICIPANTS:**

Will Burke, Environmental Senior Specialist

**STATUS OF PERMIT:**

**Active Expires June 13, 2016**

**PURPOSE OF SITE VISIT:**

Routine, Audit

**OBSERVED VIOLATIONS**

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

- 1) Winter Crop is up.
- 2) Required markers were up and borders were easily identified.
- 3) No objectionable odors or vectors were noticed during the inspection.
- 4) Access road was in good shape.
- 5) Required signage was up and easy to identify.
- 6) Applications appear to have been performed appropriately.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 796-7397

\_\_\_\_\_  
Will Burke  
*Regional Representative*

Sent on: 1-15-14		Email		Hand delivery	X	US Mail	Certified No. [ ]
------------------	--	-------	--	---------------	---	---------	-------------------