



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	<b>X</b>	<b>COUNTY: Edgecombe</b> <b>PERMIT NO.: SLAS-33-04</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

**Date of Site Inspection:** 11/7/2013    **Date of Last Inspection:** 4/10/2013

**FACILITY NAME AND ADDRESS:**

*Lonnie House  
 East Coast Rent-A-John  
 1236 Bynum Farm Road  
 Pinetops, NC 27864*

**GPS COORDINATES:**

**N:** 35.80975

**E:** -77.61016

**FACILITY CONTACT NAME AND PHONE NUMBER:**

**Name:** *Lonnie House*  
**Telephone:** *252-813-7038*  
**Email address:**  
**Fax:** *252-827-5588*

**FACILITY CONTACT ADDRESS:**

*PO Box 388 - Farmville, NC 27828*

**PARTICIPANTS:**    *Chester Cobb*

**STATUS OF PERMIT:** *Active*

**EXPIRES:**    *2/7/2015*

**PURPOSE OF SITE VISIT:** *Routine*

**STATUS OF PAST NOTED VIOLATIONS:**

No violations noted on the previous inspection conducted on 4/10/13.

**OBSERVED VIOLATIONS:**

NONE

*The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.*

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Signage present.
2. Access road was in good shape.
3. All markers were up.
4. No discharges noticed outside of permitted boundaries.
5. No spot dumps noticed or thick applications noticed.
6. Small grain was up in places. Not the best coverage. Seeds are broadcasted.
7. No application at time of discharge. pH not checked.
8. No objectionable odors noticed.
9. No change in any of the setbacks.
10. Records not checked.
11. I collected a soil sample from each of the two fields.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (919) 707-8283.

Chester R. Cobb, Soil Scientist  
Division of Waste Management, NCDENR  
*Regional Representative*

Sent on: 7/8/14		Email		Hand delivery	X	US Mail		Certified No. [ ]
-----------------	--	-------	--	---------------	---	---------	--	-------------------