



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Edgecombe PERMIT NO.: SLAS-33-06 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 11/5/2014 **Date of Last Inspection:** 11/7/2013

FACILITY NAME AND ADDRESS:

Blake Boswell
Boswell & Son Septic Tank Service Inc.
PO Box 236
Sharpsburg, NC 27878

GPS COORDINATES:

N: 35.89958

E: -77.73565

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Blake Boswell*
Telephone: *252-977-9384*
Email address: *blakebos@embarqmail.com*
Fax: *252-977-9504*

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: *Chester Cobb*

STATUS OF PERMIT: *Active*

EXPIRES: *10/11/2016*

PURPOSE OF SITE VISIT: *Routine*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 11/7/13.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Signage present as you enter the site.
2. Access road is well maintained.
3. Two corner markers down. One is by the camper and the other one is at the southwest corner of Field 2. Need to place markers back up.
4. No discharges noticed outside of the permitted boundary for the two fields.
5. No evidence of any recent applications noticed. No spot dumps or thick application noticed.
6. Small grain had been planted and was easily visible.
7. No application at time of inspection. pH not checked.
8. No objectionable odors noticed.
9. No change noticed that would affect any of the setback distances.
10. Records not checked.
11. No violations noticed. I collected soil samples from each of the two fields.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (919) 707-8283

Chester R. Cobb, Soil Scientist
Division of Waste Management, NCDENR
Regional Representative

Sent on: 12/17/14		Email		Hand delivery	X	US Mail		Certified No. []
-------------------	--	-------	--	---------------	----------	---------	--	-------------------