



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Gaston</b> <b>PERMIT NO.: SLAS 36-04</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 4/28/2015

**Date of Last Inspection:** 7/14/2014

**FACILITY NAME AND ADDRESS:**

Stanley Environmental Solutions, Inc.  
 131 Mariposa Road  
 Stanley, NC 28164

**GPS COORDINATES:** N: 35.36067 E: -81.16873

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Jim Lanier  
 Telephone: (704) 263-8186  
 Email address: jim@stanleyenviro.com  
 Fax: N/A

**FACILITY CONTACT ADDRESS:**

351 Colt Thornburg Road  
 Dallas, NC

**PARTICIPANTS:**

Connie Wylie, Jim Lanier

**STATUS OF PERMIT:**

Active – permit expired/under review

**PURPOSE OF SITE VISIT:**

Repermit

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Reviewed renewal paperwork with Jim Lanier. Discussed submitted logs/reports. Received additional site logs (including cover sheet) & waste reports.
2. Inspected disposal fields with Mr. Lanier. Fields need cut soon. The fescue appears sufficient for land application. The corner marker is hidden by vegetation at the back right corner of field 1. This was previously noted on an audit of 12/17/2013. **Please remove excess vegetation or Mr. Lanier stated that he would possibly move this marker up in front of the vegetation.** All field markers shall be clearly visible from marker to marker. It appears that the approved setbacks are being met and that the field markers are correct per the approved site map.
3. No sign of heavy application or application outside the permitted boundaries.
4. No apparent recent application. No odor noted.
5. The required signs are posted and the access road is adequate.
6. Thank you for your time.

Please contact me if you have any questions or concerns regarding this inspection report.



\_\_\_\_\_  
 Connie S. Wylie  
*Regional Representative*

Phone: (910) 433-3352

<b>Sent on:</b>		Email		Hand delivery	<b>X</b>	US Mail		Certified No. [ ]
-----------------	--	-------	--	---------------	----------	---------	--	-------------------