



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: LINCOLN</b> <b>PERMIT NO.: SLAS 55-01</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 10-22-14

**Date of Last Inspection:** 06-25-14

**FACILITY NAME AND ADDRESS:**

Dennis Hoyle Services  
 7337 Reeps Grove Church Rd.  
 Vale, NC 28168

**GPS COORDINATES:** N: 35.5330° W: 81.42381°

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Dennis Hoyle  
 Office: (704) 276-2080  
 Cell: (980) 429-0438

**FACILITY CONTACT ADDRESS:**

P.O. Box 84  
 Vale, NC 28168

**PARTICIPANTS:**

Bill Wagner, Environmental Senior Specialist – Solid Waste Section

**STATUS OF PERMIT:**

Current – Issued March 31, 2011 Expires: March 2, 2016

**PURPOSE OF SITE VISIT:**

Annual collection of soil samples from two septage land application fields.

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

None.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT  
Division of Waste Management  
Solid Waste Section

Page 2 of 3



Figure 1: Septage Land Application Site (SLAS) 55-01

**ADDITIONAL COMMENTS**

1. The access road to the application fields was well maintained.
2. One composite soil sample was collected from each of the two septage land application fields. Each sample will be analyzed for the presence of heavy metals by the *NCDA&CS Agronomic Division Soil Testing Section*.
3. Proper signage was displayed at the entrance to the site.
4. Approved setbacks are being maintained. (i.e. distances from wells, homes, property lines etc.)
5. Stakes used to mark the limits of the waste application areas are in place and well maintained. (Photo #1)
6. There was no evidence of any application of septage outside of the permitted application areas.
7. There were no objectionable odors detected during the inspection.
8. Septage appears to have been properly applied in an even manner with no evidence of any ponding or over application of waste.
9. The cover crop was well established with no bare areas.
10. Septage is currently being applied to Field #1.
11. Field #2 will soon be in need of cutting.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**



1. Looking SW across Field #1 a one of the edge-of-waste markers.



2. Looking SE (from the entrance gate) across Field #2.

- 12. No ponding of water or of septage was observed.
- 13. The nutrient management plan stipulates that both fields are to be cut “*whenever it reaches 12 inches in height or just before seedhead [sic] emergence*”.
- 14. Please ensure that, in accordance with the approved nutrient management plan, that “*areas that develop with less than 80% ground cover by fescue will be re-seeded at a rate of 25lbs./ac. no-tilled in September.*”

Please contact me if you have any questions or concerns regarding this inspection report.

Bill Wagner  
 Environmental Senior Specialist  
*Regional Representative*

Phone: 828-296-4705

Sent on: 10/24/14		Email		Hand delivery	X	US Mail	Certified No. [ ]
-------------------	--	-------	--	---------------	---	---------	-------------------

- ec: Deb Aja, Western District Supervisor – Solid Waste Section  
 Tony Gallagher, Compost & Land Application Branch Head  
 Connie Wylie, Soil Scientist – Compost & Land Application Branch  
 Liz Patterson, Compost & Land Application Branch