



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost	SLAS	X	COUNTY: Onslow PERMIT NO.: SLAS-67-12 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF		

Date of Site Inspection: 11-12-13

Date of Last Inspection: 4-2-13

FACILITY NAME AND ADDRESS:

TNT Enterprises
 PO Box 1005
 Sneads Ferry NC, 28460

GPS COORDINATES: N: 34.55424° W: °-77.42023

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Jody Thompson
 Telephone: 910-327-2556
 Email Address: N/A
 Fax: N/A

FACILITY CONTACT ADDRESS:

Same

PARTICIPANTS:

Will Burke, Environmental Senior Specialist

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine, Audit

STATUS OF PAST NOTED VIOLATIONS:

N/A

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

OBSERVED VIOLATIONS

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

1. Access road was in good shape.
2. No serious odors or vectors were present at the time of this inspection
3. Required signage was up and easy to identify.
4. Setbacks appear to be correct (not measured).
5. Winter Crop performed well..
6. **Be mindful of lower area's in the application area. Some unusually wet areas were noted.**

Please contact me if you have any questions or concerns regarding this inspection report.



Will Burke
Regional Representative

Phone: (910) 796-7397

Sent on:1-21-14		Email		Hand delivery	<input checked="" type="checkbox"/>	US Mail		Certified No. []
-----------------	--	-------	--	---------------	-------------------------------------	---------	--	-------------------