



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Pasquotank</b> <b>PERMIT NO.: SLAS-70-01</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 7/9/2014    **Date of Last Inspection:** 11/20/2013

**FACILITY NAME AND ADDRESS:**

*Edward W. Brinson  
 Brinson and Miller Inc.  
 1731 N. Road Str.  
 Elizabeth City, NC 27909*

**GPS COORDINATES:**

**N:** 36.36018

**E:** -76.25083

**FACILITY CONTACT NAME AND PHONE NUMBER:**

**Name:** *Eddie Brinson*  
**Telephone:** *252-335-7774*  
**Email address:**  
**Fax:**

**FACILITY CONTACT ADDRESS:**

*Same as above*

**PARTICIPANTS:**    *Chester Cobb*

**STATUS OF PERMIT:** *Active*

**EXPIRES:**    *4/23/2017*

**PURPOSE OF SITE VISIT:** *Routine*

**STATUS OF PAST NOTED VIOLATIONS:**

No violations noted on the previous inspection.

**OBSERVED VIOLATIONS:**

NONE

*The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.*

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Appropriate signage present at entrance to the fields.
2. Path to the field was in good shape.
3. Site managed as one field instead of three. Field not being grazed anymore.
4. All septage discharges were within the permitted boundaries of the field.
5. No spot dumps or thick applications noticed.
6. Part of the field needs to be cut and harvested for hay. Weed control needed. Some type of thistle present in the field.
7. No application at time of inspection. pH of septage not checked.
8. No objectionable odors noticed today.
9. No change noticed with any of the setbacks.
10. Records not checked.



Broadleaf weed (thistle) in the field.



Close-up of the thistle.

Please contact me if you have any questions or concerns regarding this inspection report.

*Chester R. Cobb*

Chester R. Cobb, Soil Scientist  
 Division of Waste Management, NCDENR  
**Regional Representative**

Phone: (919) 707-8283.

Sent on: 12/17/14		Email		Hand delivery	X	US Mail	Certified No. [ ]
-------------------	--	-------	--	---------------	---	---------	-------------------