



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Sampson</b> <b>PERMIT NO.: SLAS-82-14</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection: 10-15-13**

**Date of Last Inspection: 3-13-1**

**FACILITY NAME AND ADDRESS:**

C and C Septic Tank Service  
 1366 Bass Lake Road  
 Roseboro, NC 28328

**GPS COORDINATES: N: 34.96700° E: -78.42069°**

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Authur Wayne Cannady  
 Telephone: 910-596-1595  
 Email address:  
 Fax:

**FACILITY CONTACT ADDRESS:**

Same

**PARTICIPANTS:**

Will Burke, Environmental Senior Specialist

**STATUS OF PERMIT:**

Active, Expires July 22, 2016

**PURPOSE OF SITE VISIT:**

Routine, Audit

**OBSERVED VIOLATIONS**

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

- 1) No serious odors present.
- 2) Access road are in good shape.
- 3) Winter Crop has been drilled.
- 4) Applications have been performed in a professional and responsible manner
- 5) Markers are up and easy to identify
- 6) Signs look great.
- 7) Field looks great.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 796-7397

\_\_\_\_\_  
Will Burke  
*Regional Representative*

Sent on: 1-15-14		Email		Hand delivery	X	US Mail		Certified No. [ ]
------------------	--	-------	--	---------------	---	---------	--	-------------------