



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	<b>X</b>	<b>COUNTY: Wake</b> <b>PERMIT NO.: SLAS 92-01</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

**Date of Site Inspection:** 7/16/2014

**Date of Last Inspection:** 3/11/2014

**FACILITY NAME AND ADDRESS:**

Eastside Septic Cleaning Service  
 1018 Hwy 70 West  
 Garner, NC 27529

**GPS COORDINATES:** N: 35.64836 E:-78.60078

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: B.C. Raynor  
 Telephone: (919) 772-6145  
 Email address: N/A  
 Fax: (919) 773-1501

**FACILITY CONTACT ADDRESS:**

Same as above

**PARTICIPANTS:**

Connie Wylie, Everett Coates

**STATUS OF PERMIT:**

Active

**PURPOSE OF SITE VISIT:**

Routine

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

- N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The cropstand appears adequate and the field markers appear accurate.
2. No apparent land application outside the permitted boundaries and no sign of heavy application.
3. No sign of recent application & no vectors or odors noted.
4. The approved setbacks are being met.
5. The access road is adequate and the required signs are posted.

Please contact me if you have any questions or concerns regarding this inspection report.



\_\_\_\_\_  
Connie S. Wylie  
***Regional Representative***

Phone: (910) 433-3352

<b>Sent on:</b>		Email		Hand delivery	<b>X</b>	US Mail		Certified No. [ ]
-----------------	--	-------	--	---------------	----------	---------	--	-------------------