



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Wake PERMIT NO.: SLAS 92-03 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 7/22/2015

Date of Last Inspection: 3/13/2015

FACILITY NAME AND ADDRESS:

Pearce Backhoe & Septic Tank Service
 5008 Rogers Road
 Rolesville, NC 27571

GPS COORDINATES: N: 35.92178 E: -78.47310

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Frank Pearce
 Telephone: (919) 556-5018
 Email address: pearce1980@embarqmail.com
 Fax: (919) 556-0917

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Connie Wylie, Everett Coates

STATUS OF PERMIT:

Active – permit expires July 25, 2018

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. No sign of land application. Site has not been used in a long time. Prior to land application occurring setbacks & field markers shall be verified by Wake County or DWM staff. Additional field markers will be needed to clearly delineate permitted boundaries.
2. Site is not officially inactive, therefore permitted fields shall remain in compliance and annual soil samples are required.
3. The access road is adequate, however the posted sign is about to fall & **needs to be secured**.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	----------	---------	--	-------------------