



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Wilson PERMIT NO.: SLAS-98-07 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 6/3/2013 **Date of Last Inspection:** 5/2/2013

FACILITY NAME AND ADDRESS:

Myrtle Creech
Creech's Septic Tank & Grease Trap Cleaning
8973 Kirby Road
Kenly, NC 27542

GPS COORDINATES:

N: 35.59566

E: -78.07491

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Myrtle Creech*
Telephone: *252-239-0016*
Email address: *tcreech23@gmail.com*
Fax: *252-239-6514*

FACILITY CONTACT ADDRESS:

PO Box 460 - Lucama, NC 27851

PARTICIPANTS: *Chester Cobb and Donnie Creech*

STATUS OF PERMIT: *Active*

EXPIRES: *2/1/2016*

PURPOSE OF SITE VISIT: *Complaint*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 5/2/13.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

1. I investigated an odor complaint received by Michael Scott on 5/5/13. No septage odors noted around the perimeter of the permitted boundaries of the two fields. There is a small field to the north of Field B that had been disked. The two septage land application fields had the required vegetation as noted in the nutrient management plan. I also met with Donnie and Myrtle Creech and showed them the pictures that were

CONTINUE ON BACK

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

emailed to Mike. Donnie had been keeping the area between the small field and the pond mowed down. Donnie said that he will now allow the area to grow up. Myrtle and Donnie had also planted Leyland Cypress in the area between the pond and small field. I had talked to Donnie about the complaint prior to the site visit today.



Leyland Cypress trees had been planted.



The small field between Field B and the pond. Field had been disced. This field does not receive septage.



Picture shows the Leyland Cypress between the small field and the pond. Pond on the other side of the tree.

Please contact me if you have any questions or concerns regarding this inspection report.

Chester R. Cobb

Chester R. Cobb, Soil Scientist
 Division of Waste Management, NCDENR
Regional Representative

Phone: (919) 707-8283.

Sent on: 12/29/14		Email		Hand delivery	X	US Mail	Certified No. []
-------------------	--	-------	--	---------------	----------	---------	-------------------