



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Wilson PERMIT NO.: SLAS-98-07 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 10/9/2014 **Date of Last Inspection:** 11/14/2013

FACILITY NAME AND ADDRESS:

Myrtle Creech
Creech's Septic Tank & Grease Trap Cleaning
8973 Kirby Road
Kenly, NC 27542

GPS COORDINATES:

N: 35.59566

E: -78.07491

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Myrtle Creech*
Telephone: *252-239-0016*
Email address: *tcreech23@gmail.com*
Fax: *252-239-6514*

FACILITY CONTACT ADDRESS:

PO Box 460 - Lucama, NC 27851

PARTICIPANTS: *Chester Cobb and Donnie Creech*

STATUS OF PERMIT: *Active*

EXPIRES: *2/1/2016*

PURPOSE OF SITE VISIT: *Routine*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 11/14/13.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The required signage present at entrance to site.
2. Access road is well maintained.
3. Markers present.
4. No septage discharges noticed outside of the permitted boundaries for the fields.
5. No spot dumps or thick applications noticed.
6. Small grains had been planted and was up in most of Field B. Part of Field B and Field A will have to be planted in small grains. Donnie mentioned that grubs were an issue and that he has talked to someone about controlling them.
7. No application at time of inspection. pH not checked.
8. No objectionable odors noticed today.
9. No change noticed in the area that would affect setback distances.
10. Records not checked.
11. No violations noticed today. I collected soil samples from each of the two fields.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (919) 707-8283.

Chester R. Cobb, Soil Scientist
Division of Waste Management, NCDENR
Regional Representative

Sent on: 12/17/14		Email		Hand delivery	X	US Mail		Certified No. []
-------------------	--	-------	--	---------------	---	---------	--	-------------------