



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>										
Lined MSWLF		LCID		YW	<b>X</b>	Transfer		Compost	SLAS	<b>COUNTY:</b> Tyrrell <b>NOTIFICATION NO.:</b> YWN 89-001 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P	FIRM	
CDLF		Tire Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

**Date of Inspection:** 5 March 2015

**Date of Last Inspection:** 19 December 2013

**FACILITY NAME AND ADDRESS:**

Tyrrell County Wood Processing Facility  
 Smith Lane  
 Columbia, NC 27925

**GPS COORDINATES:** **N:** 35.88398 **E:** -076.23622

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Wesley Hopkins  
 252.394.6557

**FACILITY CONTACT ADDRESS:**

Tyrrell County Solid Waste Director  
 PO Box 449  
 Columbia, NC 27925

**Attn: Solid Waste**

E-mail: [wes.hopkins@tyrrellcounty.net](mailto:wes.hopkins@tyrrellcounty.net)

**PARTICIPANTS:**

Ray Williams; NCDENR-Solid Waste

**STATUS OF PERMIT:**

Active; Annual Landclearing Debris Treatment and Processing Facility Notification issued 5 June 2014; expires 31 May 2015. A completed Yard Waste Facility Annual Notification Form is due on or before 1 June 2015. For information concerning this form please contact Elizabeth Patterson; Environmental Technician with the Composting & Land Application Branch at 919.707.8286 or via e-mail at: [Elizabeth.Patterson@ncdenr.gov](mailto:Elizabeth.Patterson@ncdenr.gov)

**PURPOSE OF SITE VISIT:**

Comprehensive Facility Compliance Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

None applicable

**OBSERVED VIOLATIONS:**

No violations were observed during this Facility Compliance Inspection; please see the ADDITIONAL COMMENTS section below.

**ADDITIONAL COMMENTS:**

- 1) This Facility is a Yard Waste Facility Notification under two acres in size.
- 2) This Facility is permitted to receive:
  - a. Untreated and unpainted wood waste.
  - b. Silvicultural Waste as defined in 15A NCAC 13B .0101(41): Waste materials produced from the care and cultivation of forest trees, including bark and woodchips.
  - c. Yard Trash as defined in 15A NCAC 13B .0101(55): Solid waste resulting from landscaping and yard maintenance such as brush, grass, tree limbs, and similar vegetative material.
  - d. Yard Waste as defined in 15A NCAC 13B .0101(56): Yard trash and landclearing debris to include stumps, limbs, leaves, grass.
- 3) The Facility can receive the aforementioned wastes for processing and storage in volumes not greater than 6,000 cubic yards per quarter.
- 4) This Facility is secured by a locked gate at the facility entrance.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

YWN07002-20150204INSP

Page 2 of 3

- 5) The Facility access gate was closed and locked upon my arrival and no attendant was on-site during this Facility Compliance Inspection.



- 6) The Facility access road is of all-weather construction and is being well maintained at this time.
- 7) Proper signage is posted at the Facility entrance stating the Facility emergency contact number, listing the banned and/or excluded items, and the hours of operation.
- 8) The hours of operation for this Facility are Wednesdays from 1:00 PM to 5:00 PM and Friday and Saturday from 8:00 AM to 5:00 PM.
- 9) Vegetative waste is brought on site and staged for grinding and removal for use as mulch.
- 10) No grinding operations were underway during this Facility Compliance Inspection.
- 11) The site is generally stable with a cover crop of native warm season grasses.



- 12) No ponding water was observed during this Facility Compliance Inspection.
- 13) The vegetative waste stockpile is currently being maintained at a manageable size.
- 14) All waste materials are being maintained at a minimum of 50' from all Facility property lines.
- 15) The waste type was reviewed during this Facility Compliance Inspection. The waste stream consisted of vegetative waste and landclearing debris and no unpermitted wastes were observed on-site.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

YWN07002-20150204INSP

Page 3 of 3



- 16) A roll off container has been placed on-site for the collection of recyclable metals. This container is transported via direct haul to the metal recycling Facility as needed.
- 17) A roll off container has been placed on-site for the collection of engineered wood and treated lumber. This container is taken to the East Carolina Regional Landfill, permit #08-03 in Bertie County as needed.
- 18) Unpermitted wastes are removed from the vegetative waste stockpile for proper management.
- 19) Roll off containers are maintained on-site for the collection and management of unpermitted wastes. These containers are transported to the East Carolina Regional Landfill, permit #08-03 in Bertie County as needed.
- 20) No off site erosion was noted during this Facility Compliance Inspection.
- 21) No violations were noted during this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: [ray.williams@ncdenr.gov](mailto:ray.williams@ncdenr.gov)

***Regional Representative***

<b>Delivered on : <u>9 March 2015</u> by</b>	X	Electronic delivery		US Mail		Certified No. [ ]
--	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: [dennis.shackelford@ncdenr.gov](mailto:dennis.shackelford@ncdenr.gov)  
 Jessica Montie; Chief Compliance Officer/SWS: [jessica.montie@ncdenr.gov](mailto:jessica.montie@ncdenr.gov)

C: \2015\Tyrrell\Notifications\YWN89-001\Inspections\YWN89001-20150305INSP  
 NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

Go Green! Thank you for helping NCDENR be environmentally responsible.

One  
 North Carolina  
*Naturally*