



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Table with columns for unit types (Lined MSWLF, Closed MSWLF, CDLF, LCID, HHW, Tire T&P/Collection, YW, White goods, Tire Monofill, Transfer, Incin, Industrial Landfill, Compost, T&P, DEMO, SLAS, FIRM, SDTF) and a summary box for County (COLUMBUS), Permit No. (2401-MSWLF-1982), and File Type (COMPLIANCE).

Date of Site Inspection: February 15, 2016 Date of Last Inspection: February 25, 2015

FACILITY NAME AND ADDRESS:

Columbus County Closed MSW Landfill
Landfill Road
Whiteville, North Carolina 28472

GPS COORDINATES: N: 34.29330° W: 78.75123°

FACILITY CONTACT NAME AND PHONE NUMBER:

Mr. Danny Fowler, Public Utilities Director
910.642.2828
dfowler@columbusco.org

FACILITY CONTACT ADDRESS:

Columbus County c/o
Mr. Danny Fowler, Public Utilities Director
612 North Madison Street
Whiteville, North Carolina 28472

William Clark, County Manager
111 Washington Street
Whiteville, NC 28472
bclark@columbusco.org

PARTICIPANTS:

Wes Hare, NCDENR Solid Waste Section

STATUS OF PERMIT:

Unlined MSWLF closed 1998

PURPOSE OF SITE VISIT:

Comprehensive Inspection

STATUS OF PAST NOTED VIOLATIONS:

Not applicable

OBSERVED VIOLATIONS:

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The site is secured with a gate at the entrance; controlled access for safety.
2. The entrance and haul roads are being maintained so as to provide all-weather access.
3. The landfill side slopes and cap are being maintained so as to prevent erosion.
4. Erosion control measures are being utilized, with no offsite sedimentation noted.
5. All monitoring wells observed were locked, as required.
6. Gas is utilized for power generation and utilized on-site.
7. One area of concern was noted. There appears to be leachate staining at an area on the west facing slope, approximately 100 yards south of the roll-off container storage area. This should be investigated for issues and corrective actions taken.



Gas collection



Slopes had some small bare areas, but mostly well maintained



White goods storage allows for coolant extraction



Bare area needs examination and soil/vegetative cover

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 910-796-7405

Wes Hare
 Environmental Senior Specialist
 Regional Representative

Sent on 2/19/16	X	Email		Hand delivery		US Mail	Certified No.
-----------------	---	-------	--	---------------	--	---------	---------------

Copies: Jason Watkins, Field Operations Branch Head - Solid Waste Section
 Jessica Montie, Compliance Officer – Solid Waste Section
 Bob George, Public Utilities
 Amanda Davis, Public Utilities