

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Department of Environmental Quality**  
**Division of Waste Management - Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>COUNTY: Guilford</b> <b>PERMIT NO.: 41-02 Closed</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	<b>X</b>	HHW		White goods		Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** January 8, 2016

**Date of Last Inspection:** None

**FACILITY NAME AND ADDRESS:**

Town of Gibsonville Closed Landfill  
 1232 Springwood Church Road  
 Gibsonville, NC 27249

**GPS COORDINATES:** N: 36.08698 E: -79.54963

**FACILITY CONTACT NAME AND PHONE NUMBER:**

James (Rob) Elliott, Public Works Director – Town of Gibsonville  
 w. 336-449-7188  
 c. 336-516-4856  
 f. 336-449-4144  
[relliott@gibsonville.net](mailto:relliott@gibsonville.net)

**FACILITY CONTACT ADDRESS:**

Town of Gibsonville  
 Rob Elliott, Public Works Director  
 129 W. Main Street  
 Gibsonville, NC 27249

**PARTICIPANTS**

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)  
 Rob Elliott, Public Works Director – Town of Gibsonville  
 Ricky Wade, Street Supervisor – Town of Gibsonville

**STATUS OF PERMIT:**

Closed

**PURPOSE OF SITE VISIT:**

Post Closure Inspection

**STATUS OF PAST NOTED VIOLATIONS**

None

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Department of Environmental Quality**  
**Division of Waste Management - Solid Waste Section**

Page 2 of 2

**OBSERVED VIOLATIONS**

None

**ADDITIONAL COMMENTS**

On January 8, 2016, John Patrone met with Rob Elliott and Ricky Wade to conduct a post closure inspection of the Town of Gibsonville Closed Landfill located on Springwood Church Road in Gibsonville, Guilford County.

1. The facility is a closed municipal solid waste (MSW) landfill.
2. The facility ceased operation/acceptance of MSW on March 6, 1989.
3. The landfill is ~ 15 – 18 acres.
4. The trench method was used to dispose of MSW at the landfill.
5. The landfill cap appeared to be at ground level.
6. The landfill cap is covered with vegetative material, specifically trees and underbrush.
7. Access roads are of all-weather construction.
8. The facility is secured by a locked gate.
9. Ensure the facility permit number (41-02) and contact information is posted.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 336-776-9673

John Patrone, Environmental Senior Specialist  
 Division of Waste Management, NCDEQ

Sent on: <u>January 22, 2016</u>	X	Email		Hand delivery		US Mail	Certified No. [ ]
----------------------------------	---	-------	--	---------------	--	---------	-------------------

Electronic Copies: Deb Aja, Western District Supervisor - SWS  
 Jessica Montie, Compliance Officer – SWS  
 Ricky Wade, Street Supervisor – Town of Gibsonville (c. 336-516-4723 [rwade@gibsonville.net](mailto:rwade@gibsonville.net))