



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		COUNTY: Carteret PERMIT NO.: LCIDN-N0620- FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Inspection: 15 January 2016

Date of Last Inspection: 26 August 2014

FACILITY NAME AND ADDRESS:

Dixon Pit LCID Landfill
 2628 Hwy 24
 Newport, NC 28570

GPS COORDINATES: 34.73488 E: -076.92395

FACILITY CONTACT NAME AND PHONE NUMBER:

Curtis S Dixon
 252.247.2643

FACILITY CONTACT ADDRESS:

2628 Hwy 24
 Newport, NC 28570

Attn: Curtis Dixon

E-mail: the2dixons@earthlink.net

PARTICIPANTS:

Curtis S Dixon; Owner/Operator
 Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Notified Landclearing and Inert Debris Landfill

PURPOSE OF SITE VISIT:

Comprehensive Facility Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable.

OBSERVED VIOLATIONS:

No violations were observed during this Facility Compliance Inspection; please see ADDITIONAL COMMENTS section below.

ADDITIONAL COMMENTS:

- 1) This Facility is a Land-Clearing and Inert Debris Landfill Notification under two acres in size.
- 2) This Facility is recorded with the Carteret County Register of Deeds at: Book 1040; Page 32.
- 3) This Facility is permitted to receive for disposal:
 - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
 - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
 - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
 - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) This Facility is secured by a locked gate at the Facility entrance and has controlled access for safety. The gate was closed and locked upon my arrival.
- 6) Proper signage is posted at the facility entrance stating the Facility emergency contact number.
- 7) The Facility access road is of all-weather construction and is being managed properly at this time.
- 8) Soil has been stockpiled for use as cover adjacent to the landfill access road.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0620-201601151INSP

Page 2 of 3

- 9) This Facility has been capped and is currently not receiving waste. The Facility operator wishes to maintain its active status for possible future use.
- 10) A cover crop of native warm season grasses and coppice-type cover has been established throughout the facility. Some brush and woody vegetation has been established on portions of the landfill sideslopes. *Plans need to be underway for the mowing of the landfill cover crop and removal of the brush and other woody type vegetation. After mowing, please ensure that all landfill sideslopes have a groundcover established suitable to prevent erosion of your landfill cap system.



- 11) The Facility Disposal Boundary has been marked with brightly painted wooden stakes delineating the 2 acre disposal boundary. However, several of the markers have been knocked down. *Please re-install and maintain your Disposal Boundary Markers delineating the disposal footprint of the landfill.
- 12) The area around the toe of the slope needs to be mowed to provide for unrestricted access around the toe of the entire landfill for Facility Inspections and maintenance activities.
- 13) No off site erosion was observed during this Facility Compliance Inspection.
- 14) *Corrective measures are required as a result of this Facility Compliance Inspection.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0620-201601151INSP

Page 3 of 3

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.



Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>21 January 2016</u> by	X	Electronic delivery		US Mail		Certified No. <u> </u>
--	---	---------------------	--	---------	--	-------------------------

cc: Jessica Montie; Chief Compliance Officer/SWS: jessica.montie@ncdenr.gov

C: \2016\Carteret\Notifications\N0620\Inspections\N0620-201601151INSP
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

 Go Green! Thank you for helping NCDEQ be environmentally responsible.