

FACILITY COMPLIANCE INSPECTION REPORT
Department of Environmental Quality
Division of Waste Management - Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Cleveland PERMIT NO.: SLAS-23-11 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: October 30, 2015 Date of Last Inspection: October 09, 2014

FACILITY NAME AND ADDRESS:

Rhea's Septic Tank Service
 1134 Long Branch Road
 Kings Mountain, NC 28086

GPS COORDINATES: N: 35.20221 W: 81.45483

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Trent & Monica Rhea
 Telephone: (704) 739-5849

FACILITY CONTACT ADDRESS:

5030 Harmon Road
 Kings Mountain, NC 28086

PARTICIPANTS:

Troy Harrison, NC Solid Waste Section

STATUS OF PERMIT:

Active
 Issued: July 2, 2014
 Expires: December 3, 2018

PURPOSE OF SITE VISIT:

Inspection
 Annual Soil-Sampling

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

1. All photographs were taken by Troy Harrison on October 30, 2015.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

2. The Septage Land Application Site consists of one field totaling approximately 2.0 acres.



3. The site is permitted for land application of domestic septage and portable toilet waste.
4. The site is located on Beaver Creek Road (SR# 1325) and has accessible all-weather roads to the septage land application field covered under the permit.
5. Appropriate signage was displayed at the site.
6. **Disposal area boundaries were delineated with permanent markers with the exception of the area near the entrance and southeastern boundary. This area needs additional markers to clearly delineate from the buffer area.**
7. All septage discharges appear to have been made within the disposal area boundary. No recent septage application were observed.
8. There is no evidence of standing liquid or pooled waste. The waste appeared to be evenly distributed throughout the field.
9. No objectionable odors were observed.
10. **The nutrient management plan stated that this field is to be planted in fescue. Weeds were observed growing in the field. The nutrient management plan states that areas that develop with less than 80% groundcover by fescue be reseeded at a rate of 100 lbs/acre. You may also contact the Celveland County Cooperative Extension at 704-482-4365 for advice on field maintenance and weed control.**
11. Soil samples were collected from the field. The check for soil sampling was received.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: (828) 296-4701

 Environmental Senior Specialist
Regional Representative

Sent on: 12/4/2015		Email		Hand delivery	X	US Mail		Certified No. []
--------------------	--	-------	--	---------------	---	---------	--	-------------------

Copies: Tony Gallagher, Composting & Land Application Branch Head
 Michelle Sclafani, Solid Waste Section
 Connie Wylie, Composting & Land Application Branch