POLLUTION INCIDENT/U.S.T. LEAK REPORTING FORM

Department of Environment, Health, Natural Resources
Division of Environmental Management
GROUNDWATER SECTION

Confirm GW Contamination (Y/N) ____
Major Soil Contamination (Y/N) ✓
Minor Soil Contaminatin (Y/N) ____

Incident # 10121

Date Incident Occurred or Leak Detected 3·19·93

INCIDENT DESCRIPTION

Incident Location/Name: St. Pius Church Sisters Home

Address: 2206 N. Elm St.

City/Town: Greensboro | County: NC | Region: Guilford

Briefly Describe Incident: Soil contamination from UST containing #2 heating oil.

POTENTIAL SOURCE OWNER-OPERATOR

Potential Source Owner-Operator: Charlotte Catholic Diocese | Telephone: 704·327·7441

Company: | Street Address: P.O. Box 36776

City: Charlotte | County: Mecklenburg | State: NC | Zip Code: 28236

OWNERSHIP
0. N/A 1. Municipal 2. Military 3. Unknown (4. Private) 5. Federal 6. County 7. State

OPERATION TYPE
0. N/A 1. Public Service 2. Agricultrural 3. Residential (4. Educational/Relig) 5. Industrial 6. Commercial 7. Mining

POLLUTANTS INVOLVED

MATERIALS INVOLVED	AMOUNT LOST	AMOUNT RECOVERED
#2 heating oil		

SOURCE OF POLLUTION

PRIMARY SOURCE OF POLLUTION (Select one)
1. Intentional dump
2. Pit, pond, lagoon
(3. Leak-underground)
4. Spray irrigation
5. Land application
6. Animal feedlot
7. Source unknown
8. Septic tank
9. Sewer line
10. Stockpile
11. Landfill
12. Spill-surface
13. Well
14. Dredge spoil
15. Nonpoint source

PRIMARY POLLUTANT TYPE (Select one)
1. Pesticide/herbicide
2. Radioactive waste
3. Gasoline/diesel
(4. Heating oil)
5. Other petroleum prod.
6. Sewage/septage
7. Fertilizers
8. Sludge
9. Solid waste leachate
10. Metals
11. Other inorganics
12. Other organics

LOCATION
1. Facility
2. Railroad
3. Waterway
4. Pipeline
5. Dumpsite
6. Highway
(7. Residence)
8. Other

SETTING
1. Residential
2. Industrial
(3. Urban)
4. Rural

Site Priority Ranking: ____

D.E.M. Regional Contact: K. Gage | Signature: K. Gage | Date: 4·6·93

GW-61 Revised 3/92