


Unicon Triangle, Inc.
406 Tomlinson St.
High Point, NC 27260

Telephone:
Business Office (919) 882-3384
FAX (919) 887-5626

Concrete Orders:
High Point (919) 841-3379
Burlington (919) 226-2507

UNICON



May 11, 1993

Ms. Kelly Gage
Guilford County Department of Emergency Services
P.O. Box 18807
Greensboro, NC 27419

Dear Ms. Gage:


This letter is to update you on our progress in regards to the tank removal and release of product into the surrounding area.

Although the test reports show less than the state action level for gasoline, we are proceeding with additional testing to determine whether or not there is further contamination.

I am meeting with Mr. Wayne Watterson of S&ME, Inc. on May 13, 1993, in order to expedite further testing. I will advise as to the actions that he feels need to be taken.

I am also enclosing copies of the test reports for your files.

Very truly yours,
UNICON CONCRETE, INC.


Gary S. McLamb
Triad Area Manager

**SPECIALIZED ASSAYS
ENVIRONMENTAL**

*C504
02*



300 12th Ave., South
Nashville, TN. 37203
615-726-0177
FAX 615-726-3404

REFERRING CLIENT

Account: 5284
Piedmont Environmental Svcs.
Thad Chesson
1066 Boulder Rd.
Greensboro, NC 27419

ILLING CONTROL NUMBER (FOR LAB USE ONLY)

93-038997

PROJECT #

12345

P.O. #

AMPLERS (Signature)

Thad Chesson

PROJECT NAME

Union Concrete

FOR LAB USE ONLY
ACC #

SAMPLE DESCRIPTION

DATE

TIME

COMP

GRAB

FOCONT

ANALYSIS REQUESTED

367142

1500 gallon gas west

4/12/93

12:45

X

TRPA LO frac (5030) for gasoline

367143

1500 gallon gas east

4/12/93

12:45

X

TRPA LO frac (5030) for gasoline

Relinquished by: (Signature)

Thad Chesson

Date / Time

4/13/93 8:00am

Received by: (Signature)

Federal Express

Received for Laboratory by:

Pam Langford

Date / Time

4/14/93

Relinquished by: (Signature)

Date / Time

Received by: (Signature)

Remarks

Relinquished by: (Signature)

Date / Time

Received by: (Signature)

Relinquished by: (Signature)

Date / Time

Received by: (Signature)

For further assistance in completing the chain of custody form please refer to the instructions found on the opposite side



SPECIALIZED ASSAYS
ENVIRONMENTAL

300 12th Avenue South
Nashville, Tennessee 37203


Sample	Accession
UNICON CONCRETE 1500 GALLON GAS WEST	93 867142
Collection Date	Time Received
04/12/93	00:00 04/14/93
Referring Client	Client ID Reported
THAD CHESSON	04/16/93

Test	Result	Units	Reference Limits
TRPH GC SOIL LOW, MOD. 5030/8015	<5.0	PPM	

PIEDMONT ENVIRONMENTAL
SERVICES
P.O. BOX 18631
GREENSBORO

NC 27419

5284



SPECIALIZED ASSAYS
ENVIRONMENTAL

300 12th Avenue South
Nashville, Tennessee 37203

Sample	Accession	
UNICON CONCRETE 1500 GALLON GAS EAST	93 867143	
Collection Date	Time	Received
04/12/93	00:00	04/14/93
Referring Client	Client ID	Reported
THAD CHESSON		04/16/93

Test

Result

Units

Reference Limits

TRPH GC SOIL
LOW, MOD. 5030/8015

<5.0

PPM

PIEDMONT ENVIRONMENTAL
SERVICES
P.O. BOX 18631
GREENSBORO

NC 27419

5284

FOR TANKS IN NC

Return Completed Form To: The appropriate DEM Regional Office according to the county of the facility's location. [SEE MAP ON REVERSE SIDE OF OWNER'S COPY (PINK) FOR REGIONAL OFFICE ADDRESS].

State Use Only ID Number 1-4-1993 Date Received

INSTRUCTIONS

Complete and return within (30) days following completion of site investigation.

I. Ownership of Tank(s)

Unicon Concrete Owner Name (Corporation, Individual, Public Agency, or Other Entity) 406 Tomlinson Street Street Address Guilford County High Point NC 27260 City 919 882-3384 State Zip Code Area Code Telephone Number

II. Location of Tank(s)

High Point Plant Facility Name or Company 406 Tomlinson Street Facility ID # (if available) Street Address or State Road Guilford High Point 27260 County 919 882-3384 Area Code Telephone Number

III. Contact Person

Gary McLamb Area Manager 919 882-3384 Name Job Title Telephone No. (Area Code) Closure Contractor Piedmont Environmental Services PO Box 18631 Greensboro, NC 27419 (Name) (Address) Telephone No. (Area Code) Lab Specialized Assays 300 12th Avenue South Nashville, TN 37203 (Name) (Address) Telephone No. (Area Code)

IV. U.S.T. Information

V. Excavation Condition

VI. Additional Information Required

Table with columns: Tank No., Size in Gallons, Tank Dimensions, Last Contents, Water in Excavation (Yes/No), Free Product (Yes/No), Notable Odor or Visible Soil Contamination (Yes/No). Row 1: 1500, 9 ft x 64, in gas, x, x, x.

See reverse side of pink copy (owner's copy) for additional information required by N.C. - DEM in the written report and sketch.

VII. Check List

Check the activities completed.

- [x] Contact local fire marshal
[x] Notify DEM Regional Office before abandonment.
[x] Drain & flush piping into tank.
[x] Remove all product and residuals from tank
[x] Excavate-down to tank.
[x] Clean and inspect tank.
[x] Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps and other tank fixtures.
[x] Cap or plug all lines except the vent and fill lines.
[x] Purge tank of all product & flammable vapors.
[] Cut one or more large holes in the tanks.
[x] Backfill the area.
Date Tank(s) Permanently closed: 4/12/93
Date of Change-in-Service:

- ABANDONMENT IN PLACE
[] Fill tank until material overflows tank opening;
[] Plug or cap all openings;
[] Disconnect and cap or remove vent line
[] Solid inert material used - specify:

- REMOVAL
[x] Create vent hole
[x] Label tank
[x] Dispose of tank in approved manner
Final tank destination: Safeway Tank Disposal

VIII. Certification (Read and Sign)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Print name and official title of owner or owner's authorized representative: Thad Chesson, VP Piedmont Environmental Signature: [Signature] Date Signed: 4/15/93