


Summit Ave. Sumner
GU-4



GROUNDWATER TECHNOLOGY

Groundwater Technology, Inc.

1000 Perimeter Park Drive, Suite 1, Morrisville, NC 27560
Tel: (919) 467-2227 Fax: (919) 467-2299

FACSIMILE TRANSMISSION

This facsimile contains **CONFIDENTIAL INFORMATION** which also may be **LEGALLY PRIVILEGED** and which is intended only for the use of the Addressee(s) named below. If you are not the intended recipient of this facsimile, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that any dissemination or copying of this facsimile is strictly prohibited. If you received this facsimile in error, please notify us immediately by telephone and return the original facsimile to us at the above address via return mail. Thank you.

TO: Ms. Wang

COMPANY: NC DEHNR - GW Winston Salem

FAX#/LOCATION: 910 - 771 - 4632

PAGE: 1 of 2

FROM: Dee Switzer

DATE: 8/8/95

MESSAGE: Our corrected application follows. Thank you for calling.

NORTH CAROLINA
ENVIRONMENTAL MANAGEMENT COMMISSION
DEPARTMENT OF ENVIRONMENT, HEALTH, & NATURAL RESOURCES
APPLICATION FOR PERMIT TO CONSTRUCT A MONITORING WELL SYSTEM

Date: August 4, 1995 County Guilford

In accordance with the provisions of Article 7, Chapter 87, General Statutes of North Carolina and regulations pursuant thereto, application is hereby made for a permit to monitoring wells.

1. Name of Applicant: Sun Co. Attn: Dan Shine (Telephone: 610-859-5705)
Applicant's Mailing Address: 4041 Market St. Aston, PA 19014
2. Name of Property Owner (if different from applicant) Rabbi and Mrs. Richard Hammerman
Owner's Mailing Address: 1107 Summit Ave., Greensboro
3. Contact Person: Herb Burger, Groundwater Technology, Inc. (Telephone: 919-467-2227)
4. Location of Property: 1103 Summit Ave., Greensboro
5. Reason for Monitoring Well(s): Environmental Assessment
(ex: nondischarge permit requirements, suspected contamination, environmental assessment, etc.)
6. Type of facility or site for which the monitoring well(s) is needed: UST
(ex: nondischarge facility, waste disposal site, landfill, underground storage tank, etc.)
7. Type of contamination being monitored (if applicable): Petroleum Hydrocarbons
(ex: nutrients, organics, heavy metals, etc.)
8. Are any existing recovery wells associated with the monitoring well(s)? No If yes, how many? _____
Recovery Well Construction Permit No. _____
9. Distance to a known waste or pollution source: unknown feet
10. Are any water supply wells located less than 500 feet from the proposed monitoring wells? no
If yes, give distance: _____ feet
11. Well Driller: Rock Ray Drilling
12. Registration #: 1457
13. Driller's Address: 2971 Treway Ct., Virginia Beach, VA 23456

PROPOSED MONITORING WELL CONSTRUCTION INFORMATION

1. Total Number of Wells to be constructed: 1; (A) Number to be completed in bedrock? 0
(B) Number to be completed in unconsolidated material? _____
2. Estimated depth of well(s): 20 feet
3. Gravel or sand pack interval (if appropriate)
From 4 feet To 15 feet
4. Type of casing used: Sch. 40 PVC
(ex: PVC, stainless steel, galvanized steel, etc.)
5. Diameter of casing: 2 inches

FOR OFFICE USE ONLY	
<input type="checkbox"/> PERMITTED ACTIVITY <input type="checkbox"/> U.S.T. LEAK DETECTION <input type="checkbox"/> GROUNDWATER QUALITY STANDARDS VIOLATIONS SUSPECTED FROM UNPERMITTED ACTIVITIES <input type="checkbox"/> NOTICE OF NON-COMPLIANCE AT UNPERMITTED FACILITIES	PERMIT NO. _____ ISSUED _____ 19 _____ INCIDENT # _____