

Facility ID#:

**UST CLOSURE  
INSPECTION CHECKLIST**

Inspector's Name R. Gage

Date 3-18-93

**I SITE INFORMATION**

Facility/Site Name: Old Dominion Freight

City/Town: Greensboro

County: Guilford

Owner: Old Dominion Freight

Phone: 919-855-6990

Operator: "

Phone: "

Contractor: Four Seasons Ind.

Phone: 919-273-2718

Laboratory: Pace Labs

Phone: \_\_\_\_\_

Directions: \_\_\_\_\_

Date of scheduled UST Removal (from GW/UST-3): 1-18-93

**II UST STATUS**

Tank #:	1	2	3	4	5	6	7	8
Size:	<u>15K</u>	<u>10K</u>						
Product:	<u>antifreeze</u>	<u>motor oil</u>						

Remark Y (YES), N (NO), NA (NOT APPLICABLE), and U (UNKNOWN) for each of the following:

**III CLOSURE PROCEDURES**

U Tanks, tools, equipment bonded or grounded?  
U OSHA/Safety violations observed: \_\_\_\_\_

Y Product in piping drained into tank?  
Y Tanks properly purged? Method: \_\_\_\_\_  
Y Tanks emptied and cleaned properly?  
Y Accessible openings capped or plugged except 1/8" vent?  
NA UST(s) closed in place and filled with solid inert material?

Final destination of tank(s): Four Seasons Ind.

Final destination of product contaminated soil, contaminated water, etc. \_\_\_\_\_  
Four Seasons Ind. Services - Patten Ave.

**IV SITE DESCRIPTION**

Y Soil stained and/or petroleum odor? antifreeze tanks  
Y Contaminated soil excavated? Quantity? (estimate): \_\_\_\_\_  
N Soil samples taken of excavated soil left on site?  
 Excavated soil on plastic or trucked away? (Circle one)  
 Tank(s) condition: #1-good #2-good  
 Product line condition?: \_\_\_\_\_

**V SAMPLING LOCATION**

NA USTs < 20': one at each end?  
Y USTs > 20': one at each end & middle?  
N Samples every 20' of piping?  
N Samples under each tank island? -all dispensers are located on opposite side of bldg.  
U Water samples? (in lieu of soil samples)  
 Samples: floor, side, stockpiled soil?: \_\_\_\_\_

Facility ID#:

**VI SAMPLE COLLECTION QUALITY CONTROL**

Collection method: (Shovel, auger, back hoe):

Cooler How Preserved? (ice):

Y Tools decontaminated: (soap, Di-H<sub>2</sub>O, MEOH, organic-free H<sub>2</sub>O).

Y Chain-of-Custody form (required):

**VII SUMMARY OF SITE CONDITIONS**

N Groundwater intersected?

N Bedrock encountered?

Y Contaminated soil?

N Free product in excavation?

**VIII SAMPLES COLLECTED BY DEM PERSONNEL**

N Samples collected?

Sample locations:

XV COMMENTS: Ruptured sewer line located between tanks 1 & 2.

Truck wash area used to be located over these tanks.

Odor of solvent in soil. Sewage odor also prevalent for Tank #1. OVA 32, 11, 19 ppm w/ 32 reading closest to bldg. Tank #2 - no odor in native soil. Discoloration of backfill, however.

**DIAGRAM OF SITE INVESTIGATION AT UST CLOSURE**

Diagram should include physical structures such as roads, buildings, etc.; former location of USTs, pumps, product lines; soil sampling locations; and location of excavated soil.

Bishop

